

Unsymmetrical Torsion load due to aileron deflection at
Point C

