

ST. ADALBERT'S
CATHOLIC CHURCH



Pre-Conservation

GLASS CONDITION
INTERNAL

SURFACE ACCRETIONS
INTERNAL

<input checked="" type="checkbox"/>	A1	Surface Dirt	
<input type="checkbox"/>	A2	Rust Deposits	
<input type="checkbox"/>	A3	Pollution Crust	
<input type="checkbox"/>	A4	Guano	
<input type="checkbox"/>	A5	Vegetative Growth	
<input type="checkbox"/>	A6	Biological Growth	
<input type="checkbox"/>	A7	Leaded Light Cement	
<input type="checkbox"/>	A8	Putty	
<input type="checkbox"/>	A9	Mortar	
<input type="checkbox"/>	A10	Decorators Paint	
<input type="checkbox"/>	A11	Oily Deposits	
<input type="checkbox"/>	A12	Tape Residue	

PAINTS, STAINS & ENAMELS
INTERNAL

LEAD MATRIX
INTERNAL

PREVIOUS RESTORATIONS
INTERNAL

Location: St. Adalbert's Catholic Church
Window: #1
Panels: A-F
Date: 12/15/23
Conservators:
Gabe Goertz, Abby Meyer, Christina
Sieben, Nico Villareal, Nathan Walz

Window 1
Pre-Conservation
Diagrammatic Documentation



NOTES:

Surface dirt noted on panel A.



INTERNAL: Transmitted Light

PANEL
ORIENTATION

DIAGRAM
1.2