

ST. ADALBERT'S
CATHOLIC CHURCH



Pre-Conservation

GLASS CONDITION
INTERNAL

<input type="checkbox"/>	C1	Crack	—
<input type="checkbox"/>	C2	Hole	■
<input type="checkbox"/>	C3	Shell	
<input type="checkbox"/>	C4	Scratches	
<input type="checkbox"/>	C5	Fissure
<input type="checkbox"/>	C6	Micro Cracks	
<input type="checkbox"/>	C7	Crizzling	
<input type="checkbox"/>	C6	Crystalline Surface	
<input type="checkbox"/>	C9	Pitting	
<input type="checkbox"/>	C10	Craters	
<input type="checkbox"/>	C11	Corroded Surface	
<input type="checkbox"/>	C12	Corrosion Crust	
<input type="checkbox"/>	C13	Browning	

SURFACE ACCRETIONS
INTERNAL


PAINTS, STAINS & ENAMELS
INTERNAL

LEAD MATRIX
INTERNAL

PREVIOUS RESTORATIONS
INTERNAL

Location: St. Adalbert's Catholic Church
Window: #27 (1)
Panels: A-C
Date: 12/15/23
Conservators:
Gabe Goertz, Abby Meyer, Christina Sieben,
Nico Villareal, Nathan Waltz

Window 27 - I
Pre-Conservation
Diagrammatic Documentation



NOTES:

No glass condition damage to note.



INTERNAL: Transmitted Light

PANEL
ORIENTATION



DIAGRAM
14.1