

ST. ADALBERT'S
CATHOLIC CHURCH



Pre-Conservation

GLASS CONDITION
INTERNAL

SURFACE ACCRETIONS
INTERNAL

PAINTS, STAINS & ENAMELS
INTERNAL


LEAD MATRIX
INTERNAL

PREVIOUS RESTORATIONS
INTERNAL

R1	Adhesive Repair	—
R2	Copperfoil Repair	—
R3	Putty Repair
R4	Resin Infill	■
R5	Piece Reversed	↔
R6	Pre 19th C Insertion	
R7	19th C Insertion	
R8	Post 19th C Insertion	
R9	Coating / Consolidation	
R10	Cold Paint	
R11	Plate (Inside)	
R12	Plating on both sides	
R13	Plate (Painted)	


Location: St. Adalbert's Catholic Church
Window: #27 (1)
Panels: A-C
Date: 12/15/23
Conservators:
Gabe Goertz, Abby Meyer, Christina Sieben,
Nico Villareal, Nathan Waltz

Window 27 - I
Pre-Conservation
Diagrammatic Documentation



NOTES:

No previous restorations.



INTERNAL: Transmitted Light

PANEL
ORIENTATION



DIAGRAM
14.5