


NOTE :
There are no pullup resistors on the downstream hub lines---
You are depending on having them on the downstream devices!


NSUR - Control Board

TITLE: NS_ARM_Control_07_17_2017

Document Number: REV:

Date: 7/18/2017 1:06:46 PM Sheet: 1/1





Sheet: 1/1