

NSVR - Control Board

TITLE: NS_ARM_Control_01_10_2018

Document Number:


REV:

Date: 1/11/2018 3:14:40 PM


Sheet: 1/1

NOTE :

There are no pullup resistors on the downstream hub lines---
You are depending on having them on the downstream devices!



USB/PROGRAM/DEBUG/UART



NSUR - Control Board

TITLE: NS_ARM_Control_01_10_2018

Document Number:

REV:

Date: 1/11/2018 3:14:40 PM

Sheet: 1/1

Sheet: 1/1