

# Midwest Hose DocVault

COVER PAGE CREATED ON: 2024/01/19 at 14:00:1705694439 UTC

## INVOICE - EXPENSES SUMMARY Midwest Hose

---

VENDOR OR KEYWORD:	Houston Forklift Service
ERP Location Code:	Approved
Date:	01/19/2024
Invoice Type:	GENERIC
Invoice #:	5101
Total:	1,977.68

### --- OTHER VALUES ---

Signature --	
MODEL --	7FGU45
Tune up kit --	171.91T
TERMS --	Net 15
Labor: --	Traveled to customer location. Located unit and completed repairs per customer request. Tech removed regulator up and replaced with new regulator, and also we did tune up kit and key switch replace with new. Made final adjustments. Tested unit OK.
INVOICE # --	5101
Freight --	30.58T
TAX --	163.16
ACTIVITY --	LABOR 4
BILL TO --	Nick Elmer Midwest Hose & Specialty, Inc. 10640 Tanner Rd. Houston, Tx. 77041
DUE DATE --	02/03/2024
MAKE/HOURS --	toyota
DATE --	01/19/2024
SERIAL --	60226
Expenses: --	Job Supplies
QTY --	5
RATE --	125.00
--	+1 8325169581
TOTAL --	2,140.84

BALANCE DUE	\$2,140.84
--	
Key switch	50.40T
--	
per annum --	(1.5%
SUBTOTAL --	1,977.68
LP Regulator	1,052.92T
--	
DESCRIPTION	
--	
AMOUNT --	625.00T

Houston Forklift Service, LLC  
8222 Peekskill Ln  
Houston, TX 77075 US  
+1 8325169581  
info@houstonforkliftservicellc.com

INVOICE

**BILL TO**  
Nick Elmer  
Midwest Hose &  
Specialty, Inc.  
10640 Tanner Rd.  
Houston, Tx. 77041

**INVOICE #** 5101  
**DATE** 01/19/2024  
**DUE DATE** 02/03/2024  
**TERMS** Net 15

<b>MAKE/HOURS</b>	<b>MODEL</b>	<b>SERIAL</b>
toyota	7FGU45	60226

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
LABOR 4	Labor: Traveled to customer location. Located unit and completed repairs per customer request. Tech removed regulator up and replaced with new regulator, and also we did tune up kit and key switch replace with new. Made final adjustments. Tested unit OK.	5	125.00	625.00T
MATERIAL	Expenses: Job Supplies	1	46.87	46.87T
	LP Regulator			1,052.92T
	Tune up kit			171.91T
	Key switch			50.40T
	Freight			30.58T

Terms: Payable upon receipt. All late invoices bear an interest rate of 18% per annum (1.5% per month).	SUBTOTAL	1,977.68
	TAX	163.16
	TOTAL	2,140.84
	BALANCE DUE	<b>\$2,140.84</b>

Signature\_\_\_\_\_



# PARTS

QTY	DESCRIPTION	UNIT PRICE	PRICE
4	Spark Plugs kit	Tune up	
1	Regulator		
1	Key Switch		



HOUSTON FORKLIFT SERVICE

INVOICE: 5101

SERVICE FOR ALL  
MAKES AND MODELS

832-516-9581

info@houstonforkliftservice.com

Customer		Contact Name	
Mid West home and Specialty			
Address	10640 Tanner RD	City/State	Houston TX
Phone		Unit#	
		Hrs	
		P/O#	77041
Make	Torota	Model	7FGU45
		Serial Number	60126
Trouble Reported			
Description of Work:			

Traveled to customer location. Located crit and completed repairs per customer request. Tech removed regulator up and replaced with new regulator. and also we did tune up kit and key switch replace with it new. made final adjustments. Tested unit ok.

HOUSTON FORKLIFT SERVICE

Upon Inspection, Trained Personnel Recommends

I HAVE AUTHORITY TO ORDER THE ABOVE WORK, WHICH HAS BEEN SATISFACTORY PERFORMED, AS OUTLINED ABOVE, OR IS AGREED THAT THE SELLER WILL RETAIN TITLE TO ANY EQUIPMENT OR MATERIAL THAT MAY BE FURNISHED UNTIL FINAL PAYMENT IS MADE. IF SETTLEMENT IS NOT MADE AS AGREED, THE SELLER SHALL HAVE THE RIGHT TO REMOVE SAME AND THE SELLER WILL BE HELD HARMLESS FOR ANY DAMAGES RESULTING FROM THE REMOVAL THERE OF:

START DATE: 1/3/24 COMPLETE DATE: 1/2/24

CUSTOMER SIGNATURE

(completion of the above described work.)

Service Charge

Material

Misc.

Sub-Total

Tax

TOTAL DUE

We Appreciate Your Business