


## Mercedes Benz C 250 Sedán 2013 (204.047) L4-1.8L Turbo (271.860)

Vehículo > Dirección y suspensión > Dirección > Mecanismo de dirección > Servicio y reparación > Desmontaje y sustitución

### AR46.40-P-0400EW Revisar y reemplazar el guardapolvo de goma











MODELOS 166, 212, 218

MODELO 207 con dirección asistida eléctrica **Se muestra en el modelo 212 con dirección hidráulica** 10 Barra de acoplamiento 10f Contratuerca 11 Fuelle 11a Abrazadera interior 11b Abrazadera exterior 12 Barra de dirección interior



## Modification notes

30.3.11	Check water drain valve in steering gear, added	Operation step 2	
---------	---	------------------	--

	<b>Checking</b>		
 <b>Danger!</b>	<b>Risk of death</b> caused by vehicle slipping or toppling off of the lifting platform.	Align vehicle between columns of vehicle lift and position four support plates at vehicle lift support points specified by vehicle manufacturer.	AS00.00-Z-0010-01A
1	Raise vehicle using vehicle lift until the wheels are clear of the ground	Model 166 Model 207, 212, 218	AR00.60-P-1000GZ
2	Check boots (11)	 Do not check the boots (11) by pressing in or around the raised bead. Otherwise damage and leakages may occur.  Stretch boots (11) by turning the steering to the left and right and while doing so checking for damage (cracks, holes, chafe marks and intrusions); install a new boots (11) if necessary.	
3	Check water drain valve in steering gear	Model 166, 218, Model 207, 212 with electric power steering	AR46.20-P-0005EW
	<b>Remove/install</b>		
4	Remove track rod (10)	Model 166, 212, 218 Model 207	AR46.40-P-0200EW AR46.40-P-0200CW
5	Unscrew lock nut (10f)		
6	Detach inner clamp (11a) and outer clamp (11b) from boot (11)	 <b>Installation:</b> Model 207, 212, 218: Note positioning of inner clamp (11a) and the outer clamp (11b).	AR46.40-P-7200-01EW
7	Pull off bellows (11)	 <b>Installation:</b> Model 207, 212, 218: Note positioning of boot (11).	AR46.40-P-0400-02CW
	<b>Checking</b>		
8	Check toothed rack for signs of corrosion	 If the toothed rack is corroded, a new rack-and-pinion steering must be installed. ↓ Remove/install rack-and-pinion steering: Model 166 Model 212 with hydraulic power steering Model 207, 212 with electric power steering Model 218	AR46.20-P-0600GQ AR46.20-P-0600EW AR46.20-P-0600EL
9	Check axial joint of inside tie rod (12) for play	 If the axial joint is worn, the inner tie rod (12) must be replaced with a new one. ↓ Remove/install inner tie rod with axial joint. Model 166, 212, 218 Model 207	AR46.40-P-0201EW AR46.40-P-0201CW
10	Install in the reverse order		
11	Perform wheel alignment check	Model 166 Model 207, 212, 218	AR40.20-P-0200GQ AR40.20-P-0200EW