


Andora "D" Building Sewer



22817 LAKEVIEW DR



Performed Repair on 6" collapsed Pipe. And Cleared line of rocks and Dirt. This storm line has been Damaged for a considerable Amount of Time.

All clean outs have a meter Box installed over them. Per City.

The new sewer has $\frac{1}{8}$ " per ft Drop on the run, or flat the entire length of the sewer.