

# FRIMS Assam

## Flood Reporting And Information Management System

Assam Daily Flood Report as on 29-06-2023 at 4:00 PM								
Particulars	Situation as on 29-06-2023 (in last 24 hours)							
Rivers flowing above Danger Level (as per CWC bulletin issued at 8 AM)	Rivers flowing above danger level			Nil				
	Rivers flowing above highest flood level			Nil				
District/Sub-division Affected	No. of Districts/Sub-divisions* Affected	Name of Flood Affected Districts/Sub-divisions*			Name of Urban Flood Districts/Sub-divisions*			
	9	Bajali, Barpeta, Darrang, Goalpara, Golaghat, Jorhat, Kamrup, Lakhimpur, Sonitpur						
No. Of Revenue Circles Affected	17							
Name Of Revenue Circles Affected	District/Sub-division*	Total	Revenue Circle					
	Bajali	2	Sarupeta, Bajali					
	Barpeta	3	Chenga, Sarthebari, Barpeta					
	Darrang	1	Mangaldoi					
	Goalpara	1	Rongjuli					
	Golaghat	1	Dergaon					
	Jorhat	3	Titabor, Teok, Jorhat West					
	Kamrup	3	North Ghy, Kamalpur, Hajo					
	Lakhimpur	1	Nowboicha					
	Sonitpur	2	Chariduar, Tezpur					
	Total	17						
Villages Affected	District/Sub-division*	Total	Revenue Circle					
	Bajali	20	( Sarupeta   5 ), ( Bajali   15 )					
	Barpeta	37	( Chenga   15 ), ( Sarthebari   13 ), ( Barpeta   9 )					
	Darrang	33	( Mangaldoi   33 )					
	Goalpara	2	( Rongjuli   2 )					
	Golaghat	2	( Dergaon   2 )					
	Jorhat	19	( Titabor   5 ), ( Teok   2 ), ( Jorhat West   12 )					
	Kamrup	116	( North Ghy   6 ), ( Kamalpur   33 ), ( Hajo   77 )					
	Lakhimpur	7	( Nowboicha   7 )					
	Sonitpur	17	( Chariduar   13 ), ( Tezpur   4 )					
	Total	253						
Population And Crop Area Affected	District/Sub-division*	Male	Female	Children	Total Population	Population Details	Crop Area ( in Hect. )	Crop Area Details
	Bajali	3698	3635	610	7943	( Sarupeta   3015 ), ( Bajali   4928 )	22.00	( Sarupeta   8.00 ), ( Bajali   14.00 )
	Barpeta	8896	9043	2364	20303	( Chenga   835 ), ( Sarthebari   12853 ), ( Barpeta   6615 )	38.00	( Chenga   15.00 ), ( Sarthebari   23.00 ), ( Barpeta   0.00 )
	Darrang	0	0	0	0	( Mangaldoi   0 )	317.00	( Mangaldoi   317.00 )
	Goalpara	0	0	0	0	( Rongjuli   0 )	4.00	( Rongjuli   4.00 )
	Golaghat	0	0	0	0	( Dergaon   0 )	6.20	( Dergaon   6.20 )
	Jorhat	0	0	0	0	( Titabor   0 ), ( Teok   0 ), ( Jorhat West   0 )	57.55	( Titabor   3.34 ), ( Teok   6.50 ), ( Jorhat West   47.71 )

	Kamrup	1	1	2	4	( North Ghy   4 ), ( Kamalpur   0 ), ( Hajo   0 )	1065.13	( North Ghy   10.50 ), ( Kamalpur   66.63 ), ( Hajo   988.00 )		
	Lakhimpur	4603	4149	329	9081	( Nowboicha   9081 )	0.00	( Nowboicha   0.00 )		
	Sonitpur	158	161	87	406	( Chariduar   406 ), ( Tezpur   0 )	16.20	( Chariduar   10.20 ), ( Tezpur   6.00 )		
	Total	17356	16989	3392	37737		1526.08			
Relief Camps / Centres Opened	District/Sub-division*	Total	Relief Camp				Relief Distribution Centres			
	Barpeta	2	0(Barpeta   0)				2(Barpeta   2)			
	Kamrup	1	1(North Ghy   1)				0(North Ghy   0)			
	Sonitpur	1	0(Chariduar   0)				1(Chariduar   1)			
	Total	4	1				3			
Inmates In Relief Camps	District/Sub-division*	Total	Revenue Circlewise			Male	Female	Children	Pregnant / Lactating Mother	Person with Disability
	Kamrup	4	(Kamalpur   0), (Hajo   0), (North Ghy   4)			1	1	2	0	0
	Total	4				1	1	2	0	0
Human Lives Lost - Confirmed	Nil									
Human Lives Lost Confirmed - Death Type	Nil									
Human Lives Lost - Missing	Nil									
Human Lives Lost Missing - Type	Nil									
Animals Affected	District/Sub-division*	Total	Big	Small	Poultry					
	Bajali	5551	2904	2062	585					
	Barpeta	20913	10138	7152	3623					
	Kamrup	3850	3850	0	0					
	Sonitpur	1765	1230	535	0					
	Total	32079	18122	9749	4208					
Animals Washed Away	Nil									
Houses Damaged	Nil									
Rescue Operation	District/Sub-division*	Agency			Boats Deployed	Person Evacuated By Boats	Animal Evacuated By Boats	Helicopters Deployed	Person Evacuated By Helicopters	Medical Team Deployed
	Kamrup				0	0	0	0	0	1
	Total				0	0	0	0	0	1
Relief Distributed	District/Sub-division*	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)	Cattle Feed - Rice Bran (in Q)		
	Barpeta	0.00	0.00	0.00	0.00	0.00	21.20	0.00		
	Sonitpur	6.79	1.22	0.37	0.00	0.00	0.00	0.00		
	Total	6.79	1.22	0.37	0.00	0.00	21.20	0.00		
Relief Distributed Others	District/Sub-division*	Baby Food Liquid		Baby Food Solid		Others				
	Barpeta	0.00-Q		0.00-Q						
	Sonitpur	0.00-Q		0.00-Q						
Infrastructure Damaged -	District/Sub-division*	Number	Details							

Embankment Breached	Jorhat	1	<b>Teok</b> - Teok river left ring bund   Dakhin Dulia Gaon of Teok Mouza.   Approx. Length= 12 Feets, Date= 28-06-2023   (Long - 94.396660, Lat - 26.839715, Dept - P&RD)
	Total	1	
Infrastructure Damaged - Embankments Affected	Nil		
Infrastructure Damaged - Road	<b>District/Sub-division *</b>	<b>Number</b>	<b>Details</b>
	Barpeta	3	<b>Baghbar</b> - Mandia Barpeta Approach road to Barpalli road   Barpalli area   As per report received from PWD roads dept on 28/06/23, due to continuous heav rainfall the said road has submerged and shoulder damaged from ch 300.00m to 2000.00m. Damage occurred on 25/06/23.   (Long - 91.000363, Lat - 26.322266, Dept - PWD (Roads)), Gajia to Gobindapur road   Gajia area   As per report received from PWD roads dept on 28/06/23, due to continuous heav rainfall the said road has submerged and surface & shoulder damaged from ch 2400.00m to 3600.00m. Damage occurred on 25/06/23.   (Long - 90.974450, Lat - 26.411477, Dept - PWD (Roads)), Sidhani to Lurfuria road   Lurfuria area   As per report received from PWD roads dept on 28/06/23, due to continuous heav rainfall the said road has submerged and surface & shoulder damaged from ch 50.00m to 2000.00m. Damage occurred on 25/06/23.   (Long - 90.967008, Lat - 26.298533, Dept - PWD (Roads))
	Kamrup	1	<b>Boko</b> - Boko-Upper lumpi road   Boko-Upper lumpi road at 18th km.   Erosion of Boko- Upper Lumpi road at 18th km, length of erosion is about 30 m. Reported by AEE, PWRD, Boko Territorial Road Sub-Division on 29.06.2023.   (Long - 91.204887, Lat - 25.846658, Dept - PWD (Roads))
	Total	4	
Infrastructure Damaged - Bridge	Nil		
Infrastructure Damaged - Wildlife	Nil		
Infrastructure Damaged - Others	<b>District/Sub-division *</b>	<b>Other Details</b>	
	Bajali	<p><b>Bajali</b> - Irrigation Canal/Scheme Damaged   Siltation of main canal from Ch. 10000.00 m to ch. 14000.00 m, Deposition of silt in the main canal causing waterlogging in upstream area, "Patacharkuchi. Lat-26.505767, :Long-91.228763". This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023,</p> <p>Irrigation Canal/Scheme Damaged   Formation of Breaches at Ch 600 m of Branch canal 1 (Both Side) at Kaldiya F.I.S , Damage of Earthen branch canal 1 (both side) , Rihabari, Lat-26.610935, Long-91.198662. This report is received from Executive Engineer,Tihu Division, Irrigation,Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Formation of Breaches at Ch 2700 m ( for a length of 15 m) of Branch canal 1 (Both Side) at Kaldiya F.I.S. Damage of Earthen branch canal 1 (both side) for a length of 10 m, Baghmara Lat-26.610875,Long-91.178684. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Water Course (Brick lined) at Chainage 8330.00 M of Branch canal 1 of Kaldiya FIS. Damage of water course at BC-1 of Kaldiya FIS (Wall and Bed), Saderi, Lat-26.611542, Long- 91.178424. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Water Course (Brick lined) at Chainage 2100.00 M of Branch canal 1 of Kaldiya FIS. Damage of water course at BC-1 of Kaldiya FIS (Wall and Bed), Baghmara, Lat-26.610883, Long- 91.178660. . This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   . Damage of Water Course (Brick lined) at Chainage 2110.00 M of Branch canal 1 of Kaldiya FIS. Damage of water course at BC-1 of Kaldiya FIS (Wall and Bed), Baghmara, Lat- 26.610863, Long- 91.178691. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Water Course (Brick lined) at Chainage 8947.00 M of Branch canal 1 of Kaldiya FIS. Damage of water course at BC-1 of Kaldiya FIS (Wall and Bed), Saderi Lat-26.618564, Long- 91.179994. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Water Course (Brick lined) at Chainage 9002.00 M of Branch canal 1 of Kaldiya FIS. Damage of water course at BC-1 of Kaldiya FIS (Wall and Bed), Badankuchi, Lat-26.556948, Long- 91.176322. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Water Course (Brick lined) at Chainage 9974.00 M of Branch canal 1 of Kaldiya FIS. Damage of water course at BC-1 of Kaldiya FIS (Wall and Bed), Badankuchi, Lat-26.556854, Long- 91.177012. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu</p>	

		<p>on 28/06/2023., Irrigation Canal/Scheme Damaged   Formation of Breaches at Ch 8030 m ( for a length of 7 m) of Branch canal 1 (Both Side) at Kaldiya F.I.S. Damage of Earthen branch canal 1 (R/S) for a length of 7 m, Sadari, Lat- 26.564593, Long- 91.17423. . This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Formation of Breaches Canal Embankment at ch. 7800.00M , ch. 7200.00m, Ch. 9200.00 m,9600.00 m, 10081.00 m, 10607.00 m, 10547.00 m at BC-1 of Kaldiya FIS. Settlement of Earthen canal at various breaches of branch canal 1 of Kaldiya FIS, Sadari, Lat- 26.580739, Long- 91.174557. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Water Course (Brick lined) at Chainage 10547.00 M (L/S) of Branch canal 1 of Kaldiya FIS. Damage of water course at BC-1 of Kaldiya FIS(Wall and Bed), "Badankuchi, Lat-26.556884, Long-91.177058".This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Water Course (Brick lined) at Chainage 10532.00 M (R/S) of Branch canal 1 of Kaldiya FIS. Damage of water course at BC-1 of Kaldiya FIS (Wall and Bed), "Badankuchi, Lat- 26.556948, Long-91.176322". This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Canal Regulator gate no1, gate no 2 and gate 4 of kaldiya FIS. Damage of guide channel, rubber seal, shutter assembly and guide ruller of different canal regulator gates of Kaldiya FIS. "Rihabari, Nityanandya, "Rihabari, Nityanandya Lat-26.599615, Long-91.198868, Lat- 26.606168, Long-91.204768, Lat- 26.606256, Long-91.198758". This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Water Course (Brick lined) at Chainage 762.00 M of Branch canal 2 of Kaldiya FIS. Damage of water course at BC-2 of Kaldiya FIS(Wall and Bed), "Doisingri, Lat- 26.598690, Long-91.197790". This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Water Course (Brick lined) at Chainage 745.00 M of Branch canal 2 of Kaldiya FIS. Damage of water course at BC-2 of Kaldiya FIS (Wall and Bed), "Doisingri , Lat- 26.595325, Long-91.201421". This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Formation of Breaches at Ch 1084 m ( for a length of 12 m) of Main canal (One Side) at Kaldiya F.I.S . Damage of Earthen Main canal for a length of 12 m, Chakla , Lat- 26.515500, Long- 91.221187. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Breaches at Ch 1900 m to 2000 m of Branch canal 2 (Both Side) at Kaldiya F.I.S . Damage of Earthen branch canal 2 (both side) , "Doisingri Lat-26.598328, Long-91.197284". This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Water Course (Brick lined) at Chainage 3270.00 M of Branch canal 3 of Kaldiya FIS. Damage of water course at BC-3 of Kaldiya FIS(Wall and Bed), "Panbari , Lat- 26.558195, Long-91.19588". This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Formation of Breaches at BC-4 at chainage at 5000.00 m of kaldiya FIS. Damage of Earthen branch canal 4 (right side) , "Panbari Lat-26.551793, Long-91.204705". This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Formation of Breaches at Ch. 220.00 m embankment (R/S) of BC -3 of Kaldiya FIS. Damage of Earthen branch canal embankment , "Rihabari Lat- 26.573715, Long-91.203419". This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Formation of Breaches at ch 7372.00m , ch.10600.00m,ch. 9700.00m of main canal of kaldiya FIS. Damage of Earthen Main canal embankment., "Doisingri Lat-26.595325, Long- 91.201421". This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Brick Canal (L/S) of Bajali ELIS (Bichankuchi Point) , Damage of Brick Canal wall and bed, "Bichankuchi ,Lat-26.536961, Long-91.222291". This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   "Damage of Brick Canal of Bajali ELIS (Nityananda point 1). Damage of Brick Canal wall and bed. Nityananda, Lat-26.558001, Long-91.215498. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Brick Canal of Bajali ELIS (nityananda point no 3). Damage of Brick Canal wall and bed, Nityananda, Lat-26.541658, Long-91.213184. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   "Damage of Brick Canal of Bajali ELIS (kuwara point). Damage of Brick Canal wall and bed, kuwara, Lat-26.523904, Long-91.229141. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   "Brick Canal of Bajali ELIS (patacharkuchi point). Damage of canal bed and brick wall, patacharkuchi chakla Lat-26.519442, Long-91.2287. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Brick Canal (L/S) of Bajali ELIS (Choudhurypara Point) . Damage of Brick Canal wall and bed, "Choudhurypara Lat-26.532654, Long-91.22454". This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p>
--	--	---

		<p>Irrigation Canal/Scheme Damaged   Damage of Main Canal at Ch. 2010.00 m of Namati ELIS . Damage of Brick Canal wall and bed, "Namati, Lat-26.522915, Long-91.252802". This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Main Canal at Ch. 1757.00m of Namati ELIS. Damage of Brick Canal wall and bed., "Namati, Lat-26.523665, Long-91.252836". This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Main Canal at Ch. 510.00 m of Namati ELIS . Damage of Brick Canal wall and bed, "Namati, Lat-26.53413, Long-91.250745". This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Water Course (Brick lined) at Chainage 390.00.00 M of Branch canal of Namati ELIS. Damage of Brick Canal wall and bed, "Namati Lat-26.536175, Long-91.248164". This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Brick Canal at Tihu Dekhata DTWIS. Damage of canal bed and brick wall, "Tihu Dehkhata, Lat- 26.454168, Long-91.222997. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of suction pipe and brick lined canal at Bajali extension ELIS(Pipla Point). damage of 2 no.s of suction pipe and canal bed., "Pipla, Lat-26.573778, Long-91.224609 . This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Erosion by kaldiya river at scheme area of Bajali Extension ELIS ( Kaharpara Point). Erosion of river bank at pump house area, "Kaharpara ,Lat-26.564093, Long-91.210907. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of brick lined canal at Bajali extension ELIS(kaharpara Point). Damage of Brick Canal wall (both side) and bed, "Kaharpara Lat-26.563574, Long-91.211424". This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Brick Canal of Makhibaha DTWIS . Damage of Brick Canal wall and bed, "Makhibaha , Lat-26.44411921, Long-91.25769015. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of main canal at ch 450.00 m at Bairagi point under Barpeta ELIS. Damage of Brick Canal wall and bed, "Bairegi , Lat-26.488294, Long-91.251086. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of Brick Canal (Both Side) of Chaibari ELIS. Damage of Brick Canal wall and bed, "Chaibari, Lat- 26.607466, Long-91.2197756. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.,</p> <p>Irrigation Canal/Scheme Damaged   Damage of earthen canal along with CD repairing at Bamakhata DTWIS. Damage of earthen canal and Cross Drainage works, Bamakhata Lat-26.527041, Long-91.182308. This report is received from Executive Engineer, Tihu Division, Irrigation, Tihu on 28/06/2023.</p>
	Barpeta	<p><b>Baghbar</b> - Culvert Approach Road Damaged   1. As per report received from PWD roads dept on 28/06/23, due to continuous heav rainfall a HP culvert 3/1 at Gajia to Gobindapur road, surface and both side approach damaged from 2250m to 2270m(Length-20m, R/F-6m, Slope Ht-2m). Location coordinates- 26.411477, 90.97445. Damage occurred on 25/06/23.,</p> <p>Culvert Damaged   1. As per report received from PWD roads dept on 28/06/23, due to continuous heav rainfall a HP culvert 2/1 at Gajia to Kadong road, both side slope damaged from 1490m to 1500m(Length-10m, Slope width-1.5m, Slope Ht-2.50m). Location coordinates- 26.31898, 90.93191..</p>
	Goalpara	<p><b>Dudhnoi</b> - Irrigation Canal/Scheme Damaged   As per report submitted by Irrigation department, Kornoi RBMC earthen canal damaged at chainage 780 m, around 10 m on left side, around 3m each at 2 points on right side at Rowmari Pt. II on 28/06/2023 till date 29.06.2023, Lat. 25.942953 Long. 90.908503</p>
	Kamrup	<p><b>Boko</b> - Irrigation Canal/Scheme Damaged   Damage of canal slope at Nampathar FIS (Approx length- 10 m). Reported by AEE, Irrigation, Boko Sub-Division. Date- 28.06.2023. Co-ordinates- 25.914011, 91.114251 .,</p> <p>Irrigation Canal/Scheme Damaged   Embankment erosion at Nampathar FIS (Approx length- 6 m). Reported by AEE, Irrigation, Boko Sub-Division. Date- 28.06.2023. Co-ordinates- 25.912411, 91.112348 .,</p> <p>Irrigation Canal/Scheme Damaged   Embankment erosion and damage to canal slope at Nampathar FIS (Approx length- 5 m). Reported by AEE, Irrigation, Boko Sub-Division. Date- 28.06.2023. Co-ordinates- 25.91396, 91.114286 .</p>
	Kokrajhar	<p><b>Gossaigaon</b> - Irrigation Canal/Scheme Damaged   As per reported by AEE, Gossaigaon Sub Division (Irrigation) Gossaigaon on 26.06.2023 but report received at Circle Office on 28.06.2023 due to heavy rain Damaged Main Canal=100 Mtrs, Embankment= 50.00 Mtrs (FIS) at Village Dhauliguri,</p> <p>Irrigation Canal/Scheme Damaged   As per reported by AEE, Gossaigaon Sub Division (Irrigation) Gossaigaon on 26.06.2023 but report received at Circle Office on 28.06.2023 due to heavy rain Damaged Canal Embankment= 20 Mtrs (FIS) at Mandaria Forest Village,</p> <p>Irrigation Canal/Scheme Damaged   As per reported by AEE, Gossaigaon Sub Division (Irrigation) Gossaigaon on 26.06.2023 but report received at Circle Office on 28.06.2023 due to heavy rain Damaged L/S guide Bund= 20 Mtrs (FIS) at Village Nepalpara,</p> <p>Irrigation Canal/Scheme Damaged   As per reported by AEE, Gossaigaon Sub Division (Irrigation) Gossaigaon on 26.06.2023 but report received at Circle Office on 28.06.2023 due to heavy rain Damaged Main Canals, in four places, 60.00 Mtrs (FIS) at Village Malaguri, Oxiguri, Haraputa,</p> <p>Irrigation Canal/Scheme Damaged   As per reported by AEE, Gossaigaon Sub Division (Irrigation) Gossaigaon on 26.06.2023 but report received at Circle Office on 28.06.2023 due to heavy rain Damaged D/S, L/S Guide Bund (FIS) at Kuntola Forest Village</p>
	Tamulpur	<p><b>Goreswar</b> - Power Dept. Conductors   As per report received from SDE APDCL Rangia ESD-1, 0.5 Km</p>

		conductor at village Niz Jhargaon, 0.2km conductor at village No.3 Goreswar , 0.2 Km Conductor at village Baghdoba and 0.35 km conductor at village Betagaon was damaged . Report received on 28/06/2023., Power Dept. Poles   As per report received from SDE APDCL Rangia ESD- 1, 3 No. HT Pole at village Niz Jhargaon, 1 No. HT pole at village Betagaon, 1 No. LT Pole at Village No.3 Goreswar and 1 No. Lt pole at village Baghdoba was damaged. Report received on dated 28/06/2023.
Erosion	<b>District/Sub-division*</b>	<b>Details</b>
	Nalbari	<b>Barbhag</b> - Dhaniagog   Erosion at Dhaniagog (Ch.28th KM) L/B of river Pagladia embankment, length :150 m Approx. reported by E.E Nalbari W.R division, Nalbari Dated : 29/06/2023   15000   (Long - 26.395328, Lat - 91.483206), <b>Nalbari</b> - Barmurikona   Erosion at R/B of Pagladia at 25 th km Barmurikona area. As per the report received from Water Resource Department erosion takes place at Barmurikona Pagaldia R/B dated : 29/06/2023   0   (Long - 26.406025, Lat - 91.475978)
	Sonitpur	<b>Thelamara</b> - Baligaon Bangaligaon   Date-29/06/2023, As reported by Tezpur Water Resource Tezpur Division on 29/06/2023 Bank erosion is observed at Baligaon Bongaligaon area on the left bank area of river Belsiri,Length = 200.00m, Latitude : 26.736022, Longitude: 92.558699   0   (Long - 92.558699, Lat - 26.736022)
	Tinsukia	<b>Doomdooma</b> - Hatighuli   A fresh River Bank Erosion is being observed at Hatighuli on the left bank of river Brahmaputra since 26/06/2023 till 29/06/2023.As per information received from WR department official the affected stretch is about 200 m in length.   0   (Long - 95.537916, Lat - 27.755222)
Landslide	<b>District/Sub-division*</b>	<b>Details</b>
	Kamrup	<b>Palashbari</b> - Joramuhuria Khokhapara Road   Landslides on Joramuhuria Khokhapara Road at Ch 6500m and Ch 6515m under PWD, Mirza at reported by PWD, Mirza Sub-division on 28/6/2023   0   (Long - 91.431538, Lat - 25.892208)
Urban Flood	Nil	
*Bajali, Biswanath, Hojai and Tamulpur are sub-divisions (Independent)		