

- Add SWD Header
- Charging enabled pin not connected?
- Charge feedback resistor value wrong
- ERC
- Charging Diode Needed?
- ADCs needed?

DOne:

- Charger caps -> 220uF
- Charger rerouted feedback voltage
- Charger added cap to feedback (DNP)
- Charger: ILIM Pin now pulled to GND directly
- Charger: CH\_ENABLE Pin now pulled to 5V

Known Issues:

- Silkscreen is too large for motor sensor and USB connectors

























