



PT5, PT6, PT7, PT8 WILL HAVE TO BE LOOPED BETWEEN THE TWO CONNECTORS.  
 26 PIN CONNECTOR DOES NOT HAVE ENOUGH PASSTHROUGH LINES

comma.ai  
 you can copy this!

,

TITLE: Nissan\_Harness

Design by:

REV:

Date: not saved!

Sheet: 1/1