





A 2x2 matrix diagram. The horizontal axis is labeled 'QUALITY' and the vertical axis is labeled 'TALLER'. The top-left quadrant is labeled 'AUTHORIZE'.



| | | | | | | | | | | | | | |
|-----------|--------|---|-------------|--------------------|--|----------------------------|---------------------|---|-----------|--|------|--|--|
| QUALITY | | NOTES: Pieza libre de filos y rebabas. | | TOTAL OF PIECES | 1 Pzas. | UNLESS OTHERWISE SPECIFIED | | <div><div></div><div>JOYSON SAFETY SYSTEMS</div></div> | | <div>ALL TECHNICAL DATA DISCLOSED HERE IN IS THE PROPERTY OF JOYSON SAFETY SYSTEMS AND SHALL NOT BE USED BY ANY OTHER MANUFACTURER, PROCUREMENT OR DISCLOSURE WITHOUT WRITTEN PERMISSION OF THE OWNER.</div> <div>JOYSON TECHNICAL CENTER</div> <div>MODEL NAME: CDL001-AC SERIES No: M2021-XXX</div> <div>MACHINE NAME: CORTADORA DE LOOP</div> <div>PART NUMBER: CDL001-AC-441</div> <div>SIZE A PART NAME PART 441 REV. A</div> <div>ESCALE 1:1 DRAWING IN INCHES</div> | | | |
| | | | | ANG. PRO |  | | | | | | | | |
| | | | | | | MM +1 -1 | INCHES +004 -004 | ANGLES +1° -1° | APPROVALS | | DATE | | |
| | | | | | | MATERIAL: 6061 Aluminio | | DESIGNER | | VHGS 12/ENE/2022 | | | |
| | | | | | | SURFACE TREATMENT POLISHED | | REVIEW | | JATA 12/ENE/2022 | | | |
| | | | | | | HARDNESS N.A. | | | | | | | |
| AUTHORIZE | TALLER | REV | DESCRIPTION | DATE | APPROVED | REVIEWS | | | | | | | |