



Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Release Notes

August 21, 2015

Confidential and Proprietary Information

© Broadcom Corp., 2008, All rights reserved.
Printed in United States of America.
16340 West Bernardo Drive
San Diego, CA 92127
Phone: (858) 385-8800
Fax: (858) 385-8810

LICENSED SOFTWARE

©200x Broadcom Corporation

This program is the proprietary software of Broadcom Corporation and/or its licensors, and may only be used, duplicated, modified or distributed pursuant to the terms and conditions of a separate, written license agreement executed between you and Broadcom (an "Authorized License"). Except as set forth in an Authorized License, Broadcom grants no license (express or implied), right to use, or waiver of any kind with respect to the Software, and Broadcom expressly reserves all rights in and to the Software and all intellectual property rights therein. IF YOU HAVE NO AUTHORIZED LICENSE, THEN YOU HAVE NO RIGHT TO USE THIS SOFTWARE IN ANY WAY, AND SHOULD IMMEDIATELY NOTIFY BROADCOM AND DISCONTINUE ALL USE OF THE SOFTWARE.

Except as expressly set forth in the Authorized License,

1. This program, including its structure, sequence and organization, constitutes the valuable trade secrets of Broadcom, and you shall use all reasonable efforts to protect the confidentiality thereof, and to use this information only in connection with your use of Broadcom integrated circuit products.
2. TO THE MAXIMUM EXTENT PERMITTED BY LAW, THE SOFTWARE IS PROVIDED "AS IS" AND WITH ALL FAULTS AND BROADCOM MAKES NO PROMISES, REPRESENTATIONS OR WARRANTIES, EITHER EXPRESS, IMPLIED, STATUTORY, OR OTHERWISE, WITH RESPECT TO THE SOFTWARE. BROADCOM SPECIFICALLY DISCLAIMS ANY AND ALL IMPLIED WARRANTIES OF TITLE, MERCHANTABILITY, NONINFRINGEMENT, FITNESS FOR A PARTICULAR PURPOSE, LACK OF VIRUSES, ACCURACY OR COMPLETENESS, QUIET ENJOYMENT, QUIET POSSESSION OR CORRESPONDENCE TO DESCRIPTION. YOU ASSUME THE ENTIRE RISK ARISING OUT OF USE OR PERFORMANCE OF THE SOFTWARE.
3. TO THE MAXIMUM EXTENT PERMITTED BY LAW, IN NO EVENT SHALL BROADCOM OR ITS LICENSORS BE LIABLE FOR (i) CONSEQUENTIAL, INCIDENTAL, SPECIAL, INDIRECT, OR EXEMPLARY DAMAGES WHATSOEVER ARISING OUT OF OR IN ANY WAY RELATING TO YOUR USE OF OR INABILITY TO USE THE SOFTWARE EVEN IF BROADCOM HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES; OR (ii) ANY AMOUNT IN EXCESS OF THE AMOUNT ACTUALLY PAID FOR THE SOFTWARE ITSELF OR U.S. \$1, WHICHEVER IS GREATER. THESE LIMITATIONS SHALL APPLY NOTWITHSTANDING ANY FAILURE OF ESSENTIAL PURPOSE OF ANY LIMITED REMEDY.

INTRODUCTION

Prepared for Netapp BSA release

CUSTOMER SUPPORT PORTAL (CSP)

Customers can submit enhancements, changes and/or defects against releases of software or firmware via the Broadcom Customer Support Portal (CSP). CSP cases are replicated into the Broadcom Bluetooth engineering change management database for review by the engineering community and change control boards.

If your project or program is not listed inside the CSP please contact your Broadcom representative whom can configure the CSP system for use with your unique needs.

To start using the CSP please visit <http://support.broadcom.com>.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Critical

BLTH03456967

Subsystem: Stack

Version Found:

N/A

Version(s) Released:

BSA0107_00.01.00

Version Found:

BSA0107_00.01.00

Version(s) Released:

BSA0107_00.01.00

Headline:

Fix compile errors

Release Note:

Fixed compile errors.

BLTH03462970

Subsystem: BSA

Version Found:

N/A

Version(s) Released:

BSA0107_00.02.00

Version Found:

BSA0107_00.02.00

Version(s) Released:

BSA0107_00.02.00

Headline:

QtApp MAP client failed to connect to iPhone

Release Note:

Fixed MAP client connection failure with iPhone.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Critical

BLTH03463084

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.10.00

Version Found: BSA01062_01.10.00

Version(s) Released: BSA01062_01.10.00

Headline:

Fix build errors

Release Note:

Fixed build errors

BLTH03463119

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.10.00

Version Found: BSA01062_01.10.00

Version(s) Released: BSA01062_01.10.00

Headline:

Fix build errors

Release Note:

Fixed build errors

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Critical

BLTH03463334

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.10.00

Version Found: BSA01062_01.10.00

Version(s) Released: BSA01062_01.10.00

Headline:

Fix build errors

Release Note:

Fix build issues

BLTH03464193

Subsystem: A2DP

Version Found: N/A

Version(s) Released: BSA01062_01.11.00

Version Found: BSA01062_01.10.00

Version(s) Released: BSA01062_01.11.00

Headline:

QTAApp 3AVk Connection Feature - Floating Point exception and QTAApp crash

Release Note:

Fixed issue

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Critical

BLTH03464603

Subsystem: BSA

Version Found: BSA01062_01.11.00

Version(s) Released: BSA01062_01.12.00

Version Found: BSA01062_01.11.00

Version(s) Released: BSA01062_01.12.00

Headline:

3-AVK - Disconnecting one AV connection causes disconnection of other AV connections

Release Note:

Fixed 3AVK connection issues.

BLTH03465682

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.16.00

Version Found: BSA01062_01.12.00

Version(s) Released: BSA01062_01.16.00

Headline:

BSA01062 - Add AAC support

Release Note:

Added AAC codec support for 3AVK connections

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Critical

BLTH03466939

Subsystem: A2DP

Version Found: N/A

Version(s) Released: BSA0106_01.56.00

Version Found: BSA0106_01.54.00

Version(s) Released: BSA0106_01.56.00

Headline:

[BSA Linux Automotive] When QT App is in Phone role, A2DP audio is not heard in headset

Release Note:

Fixed bug related to av-avk relay. Function was indicating that av-avk was enabled but not ready so server did not route any audio.

BLTH03468039

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.19.00

Version Found: BSA01062_01.18.00

Version(s) Released: BSA01062_01.19.00

Headline:

Fix Nucleus compile issues

Release Note:

Fix nuclues rc related compile issue

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Critical

BLTH03468915

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.03.00

Version Found: BSA0107_00.02.00

Version(s) Released: BSA0107_00.03.00

Headline:

BSA loses first key from BLE remote

Release Note:

Fixed the problem that BSA loses first key from BLE remote.

BLTH03470172

Subsystem: avk

Version Found: N/A

Version(s) Released: BSA01062_01.21.00

Version Found: BSA01062_01.19.00

Version(s) Released: BSA01062_01.21.00

Headline:

add bd_addr on BTA_AVK_SUSPEND_EVT for 3 AVK

Release Note:

add bd_addr on BTA_AVK_SUSPEND_EVT.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Critical

BLTH03470303

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.58.00

Version Found: BSA0106_NIGHTLY_2015-06-26

Version(s) Released: BSA0106_01.58.00

Headline:

Remove unnecessary codec configuration

Release Note:

Removed unnecessary codec configuration from a customer project

BLTH03471156

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.58.00

Version Found: BSA0106_NIGHTLY_2015-07-02

Version(s) Released: BSA0106_01.58.00

Headline:

kernel crash was happened at removing btusb which was enabled autopm

Release Note:

Fix btusb_disconnect function which access NULL pointer when btusb uses autopm mode

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Critical

BLTH03471610

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.23.00

Version Found: BSA0106_NIGHTLY_2015-07-02

Version(s) Released: BSA01062_01.23.00

Headline:

kernel crash was happened at removing btusb which was enabled autopm

Release Note:

Fix btusb_disconnect function which access NULL pointer when btusb uses autopm mode

BLTH03471779

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.03.00

Version Found: BSA0107_00.03.00

Version(s) Released: BSA0107_00.03.00

Headline:

Compile error fix

Release Note:

Compile error fix

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Critical

BLTH03471999

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.03.00

Version Found: BSA0107_00.03.00

Version(s) Released: BSA0107_00.03.00

Headline:

Compile error fix

Release Note:

Compile error fix.

BLTH03472359

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.04.00

Version Found: BSA0107_00.03.00

Version(s) Released: BSA0107_00.04.00

Headline:

Authentication required when connecting to a paired iPhone

Release Note:

Fixed an issue that authentication is requested when connecting to a paired device.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Critical

BLTH03473272

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.05.00

Version Found: BSA0106_NIGHTLY_2015-07-20

Version(s) Released: BSA0107_00.05.00

Headline:

Make option to configure BLE Server profile security

Release Note:

Make option to configure BLE Server profile security

BLTH03473273

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.23.00

Version Found: BSA0106_NIGHTLY_2015-07-20

Version(s) Released: BSA01062_01.23.00

Headline:

Make option to configure BLE Server profile security

Release Note:

Make option to configure BLE Server profile security

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Critical

BLTH03475930

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.06.00

Version Found: BSA0107_00.05.00

Version(s) Released: BSA0107_00.06.00

Headline:

BSA_SecAddDevice function with ble device was failed

Release Note:

Fixed definitions on libbsa.txt to sync BLE Key structure

BLTH03476058

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.06.00

Version Found: BSA0107_00.06.00

Version(s) Released: BSA0107_00.06.00

Headline:

Add build flag on bsa_sv_sec_dump_le_key_values function

Release Note:

Add build flag on bsa_sv_sec_dump_le_key_values function

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects	Critical
-------------------------	-----------------

BLTH03476111

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.06.00

Version Found: BSA0107_00.06.00

Version(s) Released: BSA0107_00.06.00

Headline:

Fix compile error on BLE key dump function on bsa_sec.c file

Release Note:

Fix compile error on BLE key dump function on bsa_sec.c file

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03065878

Subsystem: BLE - GATT

Version Found: N/A

Version(s) Released: BSA0106_01.54.00

Version Found: BSA0106_00.48.00

Version(s) Released: BSA0106_01.54.00

Headline:

bsa0106 app_ble_wifi when the app_ble initiator app quits, the responder gets a disconnection event with BSA_BLE_SE_DISCONNECT_EVT status:19

Release Note:

Change disconnection display message

BLTH03447857

Subsystem: AVRCP

Version Found: N/A

Version(s) Released: BSA01062_01.01.00

Version Found: N/A

Version(s) Released: BSA01062_01.01.00

Headline:

BSA AVRCP does not function correctly when connecting from Phone side.

Release Note:

Added code to support the BTA_AVK_RC_PEER_FEAT_EVT event

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03449500

Subsystem: A2DP

Version Found: BSA01062_01.01.00

Version(s) Released: BSA01062_01.03.00

Version Found: BSA01062_01.01.00

Version(s) Released: BSA01062_01.03.00

Headline:

AVDT_Set_Configuration failing when Peer AV Sink tries to reconnect

Release Note:

Need to add copy protection flag to the supported features when enabling A2DP Source

BLTH03449857

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.02.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA01062_01.02.00

Headline:

meta-data and browsing does not work when connected from iPhone

Release Note:

Corrected condition because of which bsa server was not registering for notification and allowing browsing.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03450079

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.10.00

Version Found: BSA01062_01.01.00

Version(s) Released: BSA01062_01.10.00

Headline:

Add support for 3 Simultaneous A2DP+AVRCP Connections

Release Note:

Added support for 3 Simultaneous A2DP+AVRCP Connections

BLTH03450113

Subsystem: AVCTP

Version Found: BCM4349B0_002.001.014.0024.0000

Version(s) Released: BSA01062_01.02.00

Version Found: BTE0323_00.38.00

Version(s) Released: BSA01062_01.02.00

Headline:

[BTE0323]: From Source try to re-open the RC observed ccb 1 not allocated and RC open failed.

Release Note:

Port fix from BTE

Need to set `bta_avk_cb.rc_acp_handle = BTA_AVK_RC_HANDLE_NONE;` to register a listening AVRCP channel.

There are some problems in the merge process, in the original CR, the one is there but after merge it was not there.....

http://gerrit-sw-8094.irv.broadcom.com:8094/#/c/1929/1/avk/bta_avk_act.c

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03451006

Subsystem: A2DP

Version Found: N/A

Version(s) Released: BSA01062_01.04.00

Version Found: BSA01062_01.03.00

Version(s) Released: BSA01062_01.04.00

Headline:

A2DP and call audio mixed in QT App - Multi Profile Multi Device scenario

Release Note:

Handle pause/play music when HF and AVK are connected to different devices

BLTH03451144

Subsystem: A2DP

Version Found: BSA01062_01.03.00

Version(s) Released: BSA01062_01.04.00

Version Found: BSA01062_01.03.00

Version(s) Released: BSA01062_01.04.00

Headline:

[BSA_Linux_Automotic]Music played through A2DP source(Nokia Lumia) when disconnected and reconnected with QT App

Release Note:

Use BTA SIG_OPEN and SIG_CLOSE event in BSA server to send notiications to BSA client (instead of BTA AV_OPEN/CLOSE) because of white paper related changes.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03451166

Subsystem: AVCTP

Version Found: N/A

Version(s) Released: BSA01062_01.04.00

Version Found: BSA01062_01.03.00

Version(s) Released: BSA01062_01.04.00

Headline:

BSA_AvStart fails multiple times(error 702) when next button is pressed from headset

Release Note:

After stoppping streaming, wait for STOP event before starting streaming.

BLTH03458202

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.02.00

Version Found: BSA0107_00.01.00

Version(s) Released: BSA0107_00.02.00

Headline:

Merge latest updates from BTE323 and BSA01062 to BSA0107

Release Note:

Merged latest updates from BTE323 and BSA01062 to BSA0107.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03458748

Subsystem: BTA AVK

Version Found: N/A

Version(s) Released: BSA0106_01.57.00

Version Found: BSA01062_01.06.00

Version(s) Released: BSA0106_01.57.00

Headline:

Typographical error when sending BTA_AVK_RC_PEER_FEAT_EVT.

Release Note:

set peer role instead of local role at BTA_AVK_RC_PEER_FEAT_EVT.

BLTH03458757

Subsystem: avk

Version Found: N/A

Version(s) Released: BSA01062_01.23.00

Version Found: BSA01062_01.05.00

Version(s) Released: BSA01062_01.23.00

Headline:

BSA_AVK_STOP_EVT is recieved when 6 => AVK Start option chosen in app_avk

Release Note:

AVK start and stop methods are obsolete. The AV whitepaper recommendation is that only AV source starts and stops the stream. The AV sink should use AVRCP pass thru commands play and stop. The menu is removed.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03460757

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.53.00

Version Found: BSA0106_01.51.00

Version(s) Released: BSA0106_01.53.00

Headline:

"Full Band Fast Scan" not working in app_fm

Release Note:

Removed the full band fast scan function from the app_fm sample app because it is not fully implemented in the app layer.

BLTH03461463

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.53.00

Version Found: BSA0106_NIGHTLY_2015-04-23

Version(s) Released: BSA0106_01.53.00

Headline:

Add ble close function to customer project

Release Note:

Add ble close function to customer project

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03462331

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.53.00

Version Found: BSA0106_NIGHTLY_2015-05-05

Version(s) Released: BSA0106_01.53.00

Headline:

fix build error on app_fmr

Release Note:

fix build error on app_fmr

BLTH03462486

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.54.00

Version Found: BSA0106_NIGHTLY_2015-05-06

Version(s) Released: BSA0106_01.54.00

Headline:

Implement dual mode RCU fw upgrade routine

Release Note:

Implement dual mode RCU fw upgrade routine

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03462895

Subsystem: USB

Version Found: N/A

Version(s) Released: BSA0106_01.54.00

Version Found: BSA0106_NIGHTLY_2015-05-07

Version(s) Released: BSA0106_01.54.00

Headline:

btusb0 in /proc/driver/btusb directory is not shown if more than 2 BT module is plugged in.

Release Note:

Modified proc file update sequence.
/proc/driver/btusb is created/removed at insmod/rmmod.
btusbX is created/removed at USB probe/disconnect.

BLTH03462965

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.54.00

Version Found: BSA0106_NIGHTLY_2015-05-07

Version(s) Released: BSA0106_01.54.00

Headline:

Create a menu in app_hh to send HID_Control request

Release Note:

Add one menu in app_hh to send HID_Control request

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03462988

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.10.00

Version Found: BSA0106_NIGHTLY_2015-05-07

Version(s) Released: BSA01062_01.10.00

Headline:

Create a menu in app_hh to send HID_Control request

Release Note:

Create a menu in app_hh to send HID_Control request

BLTH03463815

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.54.00

Version Found: BSA0106_NIGHTLY_2015-05-15

Version(s) Released: BSA0106_01.54.00

Headline:

Create a customer project for Android OS

Release Note:

Create a customer project for Android OS

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03463929

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.11.00

Version Found: BSA01062_01.10.00

Version(s) Released: BSA01062_01.11.00

Headline:

Fix 3-AVK connection issues

Release Note:

Fixed 3-AVK connection issues

BLTH03464151

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.54.00

Version Found: BSA0106_NIGHTLY_2015-05-18

Version(s) Released: BSA0106_01.54.00

Headline:

Create a new project folder

Release Note:

Customer folder was created

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03464181

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.54.00

Version Found: BSA0106_NIGHTLY_2015-05-20

Version(s) Released: BSA0106_01.54.00

Headline:

Customer sample application update for BT RCU OTA update

Release Note:

Add function to OTA update for fastboot support BT remote.

BLTH03464194

Subsystem: A2DP

Version Found: N/A

Version(s) Released: BSA01062_01.12.00

Version Found: BSA01062_01.10.00

Version(s) Released: BSA01062_01.12.00

Headline:

3AVK Connections: Panasonic P81 is getting disconnected when a second phone is connected

Release Note:

Fixed connection issues

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03465194

Subsystem: A2DP

Version Found: N/A

Version(s) Released: BSA01062_01.16.00

Version Found: BSA01062_01.11.00

Version(s) Released: BSA01062_01.16.00

Headline:

QTApp 3AVK - Connecting to AV source sometimes fails with
BSA_AVK_OPEN_EVT status 0x325

Release Note:

Fixed connection issues

BLTH03465198

Subsystem: A2DP

Version Found: BSA01062_01.11.00

Version(s) Released: BSA01062_01.23.00

Version Found: BSA01062_01.11.00

Version(s) Released: BSA01062_01.23.00

Headline:

3AVK Connection QT App -Nokia Lumia 800 Music is played through AV source
when connected to QTAPP

Release Note:

Resolved the issue where sometimes audio source does not automatically open
AVDTP connection.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03465681

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.18.00

Version Found: BSA01062_01.12.00

Version(s) Released: BSA01062_01.18.00

Headline:

BSA01062 - Fix Nucleus Build errors

Release Note:

Fixed Nucleus compile issues

BLTH03465935

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.14.00

Version Found: BSA01062_01.12.00

Version(s) Released: BSA01062_01.14.00

Headline:

Customer request for new BSA API to periodically monitor RSSI of connected devices

Release Note:

Added BSA API to allow for periodically monitoring the RSSI of connected clients.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03466050

Subsystem: A2DP

Version Found: N/A

Version(s) Released: BSA01062_01.15.00

Version Found: BSA01062_01.14.00

Version(s) Released: BSA01062_01.15.00

Headline:

3AVK Connection - Audio switching not happening if AV Src2 and 3 were connected while AV Source 1 was playing

Release Note:

Fixed issues with 3 AVK connections

BLTH03466426

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.55.00

Version Found: BSA0106_NIGHTLY_2015-06-02

Version(s) Released: BSA0106_01.55.00

Headline:

Fix for bsa_server segmentation fault on 64bit linux machine.

Release Note:

In uipc_shm.c, wrong header file referred. Therefore changed define

```
#if defined(BSA_ANDROID) || (BSA_ANDROID == TRUE)
to
#if defined(BSA_ANDROID) && (BSA_ANDROID == TRUE)
```

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03466539

Subsystem: USB

Version Found: N/A

Version(s) Released: BSA0106_01.55.00

Version Found: BSA0106_NIGHTLY_2015-06-02

Version(s) Released: BSA0106_01.55.00

Headline:

dequeue btusb rx buffer when BTUSB open

Release Note:

add btusb rx data dequeue routine at btusb open.

BLTH03467141

Subsystem: BTA DG

Version Found: N/A

Version(s) Released: BSA0106_01.57.00

Version Found: BSA0106_01.54.00

Version(s) Released: BSA0106_01.57.00

Headline:

When app_dg is connected as SPP server to a peer, it is not able to connect as a client to another SPP server

Release Note:

This issue is a result of the SPP service name the app_dg is attempting to connect with. The app generates a service name based on the connection number, the service names must match for the connection to happen. Fixed this by letting the user specify the service name or choose no service name.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03467500

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.17.00

Version Found: BSA01062_01.16.00

Version(s) Released: BSA01062_01.17.00

Headline:

Disable AAC support by default

Release Note:

Disabled AAC support by default. Support is enabled on a need basis in customer specific settings file.

BLTH03467642

Subsystem: AVRCP

Version Found: N/A

Version(s) Released: BSA01062_01.18.00

Version Found: BTE0324_NIGHTLY_2015-06-05

Version(s) Released: BSA01062_01.18.00

Headline:

Merge changes from BTE

Release Note:

BTA RC needs to check both roles(CT/TG) on the peer device and open AVRCP accordingly
Fix some crash found during UPF

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03467892

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.57.00

Version Found: BSA0106_NIGHTLY_2015-06-11

Version(s) Released: BSA0106_01.57.00

Headline:

Low power mode was not changed to deassert

Release Note:

Modified definition check routine to call HCILP_IsTxDoneCpltd function

BLTH03468112

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.57.00

Version Found: BSA0106_NIGHTLY_2015-06-14

Version(s) Released: BSA0106_01.57.00

Headline:

Create a customer project folder

Release Note:

Create a customer project folder

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03468519

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.57.00

Version Found: BSA0106_NIGHTLY_2015-06-16

Version(s) Released: BSA0106_01.57.00

Headline:

VSC send with simple_app fails on BigEndian Platform

Release Note:

The 'simple_app --vsc XXXXXX' command fails on BigEndian platform. The same problem exists with the --hci command

There is a problem to extract the OpCode (which is on 16 bits).

The root cause is that the sscanf function requires an 'int pointer'. But we pass an 'UINT16 pointer'.

On BigEndian platform, the sscanf function fills the third and forth bytes following the pointer (potential memory corruption also).

BLTH03468695

Subsystem: A2DP

Version Found: N/A

Version(s) Released: BSA01062_01.22.00

Version Found: BSA01062_01.19.00

Version(s) Released: BSA01062_01.22.00

Headline:

ERROR bsa_media_task_aa_process_rx_frame :When the A2DP source is already streaming when QT App connects, then audio not routed

Release Note:

Fixed the following issues

1) Unknown transcoding error

2) get_buf crash and

3) Audio doesn't play on sink if the the source is already playing when connected.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03468703

Subsystem: A2DP

Version Found: BSA01062_01.19.00

Version(s) Released: BSA01062_01.22.00

Version Found: BSA01062_01.19.00

Version(s) Released: BSA01062_01.22.00

Headline:

QT Application Phone role : A2DP volume increase when HS connects and A2DP doesnt resume after HS audio close

Release Note:

Modified qt app to resume audio after HS audio is closed if it was playing when HS audio was opened. Change in audio volume was not reproducible.

BLTH03469389

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.57.00

Version Found: BSA0106_NIGHTLY_2015-06-23

Version(s) Released: BSA0106_01.57.00

Headline:

BSA always grant BLE security even though authorization reply is BSA_SEC_NOT_AUTH

Release Note:

BSA always grant BLE security even though authorization reply is BSA_SEC_NOT_AUTH

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03469450

Subsystem: RFCOMM

Version Found: N/A

Version(s) Released: BSA0106_01.57.00

Version Found: BTE0324_NIGHTLY_2015-06-22

Version(s) Released: BSA0106_01.57.00

Headline:

[BTE0324] RFCOMM needs to check whether multiplexer channel exists before allowing opening other DLCs

Release Note:

RFCOMM needs to check whether multiplexer channel exists before allowing opening other DLCs

BLTH03469451

Subsystem: RFCOMM

Version Found: N/A

Version(s) Released: BSA01062_01.20.00

Version Found: BTE0324_NIGHTLY_2015-06-22

Version(s) Released: BSA01062_01.20.00

Headline:

[BTE0324] RFCOMM needs to check whether multiplexer channel exists before allowing opening other DLCs

Release Note:

RFCOMM needs to check whether multiplexer channel exists before allowing opening other DLCs

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03469539

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.58.00

Version Found: BSA0106_NIGHTLY_2015-06-23

Version(s) Released: BSA0106_01.58.00

Headline:

Add AG profile on customer project

Release Note:

Add AG profile on customer project

BLTH03469736

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.58.00

Version Found: BSA0106_NIGHTLY_2015-06-24

Version(s) Released: BSA0106_01.58.00

Headline:

Add Vendor specific command to configure PCM and SCO interface

Release Note:

Add two menus on app_tm

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03469785

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.58.00

Version Found: BSA0106_NIGHTLY_2015-06-24

Version(s) Released: BSA0106_01.58.00

Headline:

PBS vCard listing send duplicated entries when there are large amount of contacts

Release Note:

Resolved the problem that PBS vCard listing send duplicated entries when there are large amount of contacts.

BLTH03470213

Subsystem: AVRCP

Version Found: N/A

Version(s) Released: BSA01062_01.21.00

Version Found: BSA01062_01.19.00

Version(s) Released: BSA01062_01.21.00

Headline:

Change BTA_RC_DISC_BUF_SIZE due to SDP DB full occurred.

Release Note:

change rc disc buffer size.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03470305

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.58.00

Version Found: BSA0106_NIGHTLY_2015-06-26

Version(s) Released: BSA0106_01.58.00

Headline:

Fix connection param request command handle routine

Release Note:

Fix connection param request command handle routine

BLTH03470599

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.59.00

Version Found: BSA0106_01.57.00

Version(s) Released: BSA0106_01.59.00

Headline:

Port Nucleus Patches to mainline

Release Note:

Ported followed Nucleus derived fixes to mainline

using BTA_DmReadRemoteDeviceName like as BTLA.

add rc peer open event

add GKI timer for nucleus

Reg Noti for Track changed is rejected in BB9700.

send a2dp close ind to UI when disconnected after signaling channel

connected(befor media open)

add addr on avk rc open event

allow rc disconnect even a2dp ready state

typographical error when sending BTA_AVK_RC_PEER_FEAT_EVT

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03471291

Subsystem: A2DP

Version Found: N/A

Version(s) Released: BSA01062_01.23.00

Version Found: BSA01062_01.21.00

Version(s) Released: BSA01062_01.23.00

Headline:

Issue with absolute volume and multiple AVK connection feature

Release Note:

Fixed the issue where connection to a second audio source overrides the absolute current playing volume set by the first audio source.

BLTH03471795

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.58.00

Version Found: BSA0106_NIGHTLY_2015-07-09

Version(s) Released: BSA0106_01.58.00

Headline:

Add option in btdl tool to do not download MiniDriver

Release Note:

Some new BT Chips (e.g. 20703/20704) do not need a MiniDriver to be downloaded. The --nominidrv option has been added to the btdl tool.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03471887

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.58.00

Version Found: BSA0106_NIGHTLY_2015-07-09

Version(s) Released: BSA0106_01.58.00

Headline:

Add headless mode function in customer project

Release Note:

Add headless mode feature in customer project

BLTH03471905

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.03.00

Version Found: BSA0106_NIGHTLY_2015-07-09

Version(s) Released: BSA0107_00.03.00

Headline:

Add headless mode function in customer project

Release Note:

Add headless mode feature in customer project

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03471909

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.23.00

Version Found: BSA0106_NIGHTLY_2015-07-09

Version(s) Released: BSA01062_01.23.00

Headline:

Add headless mode function in customer project

Release Note:

Add headless mode feature in customer project

BLTH03471911

Subsystem: avk

Version Found: N/A

Version(s) Released: BSA01062_01.23.00

Version Found: BSA01062_01.22.00

Version(s) Released: BSA01062_01.23.00

Headline:

compile error fix in customer project

Release Note:

Build error fix

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03471944

Subsystem: Unknown

Version Found: N/A

Version(s) Released: BSA01062_01.24.00

Version Found: BSA01062_01.23.00

Version(s) Released: BSA01062_01.24.00

Headline:

3-AVK - Disconnecting one AV connection causes pausing of audio from other AV connection.

Release Note:

Resolved the issue where disconnecting one AV connection causes pausing of audio from other AV connection.

BLTH03472002

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.23.00

Version Found: BSA0106_NIGHTLY_2015-07-09

Version(s) Released: BSA01062_01.23.00

Headline:

Add option in btdl tool to do not download MiniDriver

Release Note:

Some new BT Chips (e.g. 20703/20704) do not need a MiniDriver to be downloaded. The --nominidrv option has been added to the btdl tool.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03472003

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.04.00

Version Found: BSA0106_NIGHTLY_2015-07-09

Version(s) Released: BSA0107_00.04.00

Headline:

Add option in btdl tool to do not download MiniDriver

Release Note:

Some new BT Chips (e.g. 20703/20704) do not need a MiniDriver to be downloaded. The --nominidrv option has been added to the btdl tool.

BLTH03472123

Subsystem: avk

Version Found: N/A

Version(s) Released: BSA0107_00.04.00

Version Found: BSA0107_00.03.00

Version(s) Released: BSA0107_00.04.00

Headline:

compile error fix in customer project

Release Note:

Build error fix

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03472184

Subsystem: A2DP

Version Found: N/A

Version(s) Released: BSA0106_01.59.00

Version Found: BSA0106_NIGHTLY_2015-07-13

Version(s) Released: BSA0106_01.59.00

Headline:

Add Delay report support for the AV Source side of A2DP

Release Note:

Pass Delay report information from the AV Callout to the application level

BLTH03472233

Subsystem: A2DP

Version Found: N/A

Version(s) Released: BSA01062_01.23.00

Version Found: BSA0106_NIGHTLY_2015-07-13

Version(s) Released: BSA01062_01.23.00

Headline:

Add Delay report support for the AV Source side of A2DP

Release Note:

Pass Delay report information from the AV Callout to the application level

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03472234

Subsystem: A2DP

Version Found: N/A

Version(s) Released: BSA0107_00.04.00

Version Found: BSA0106_NIGHTLY_2015-07-13

Version(s) Released: BSA0107_00.04.00

Headline:

Add Delay report support for the AV Source side of A2DP

Release Note:

Pass Delay report information from the AV Callout to the application level

BLTH03472416

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.23.00

Version Found: BSA0106_NIGHTLY_2015-07-13

Version(s) Released: BSA01062_01.23.00

Headline:

Create an API to make connection as high priority

Release Note:

Created an API to make connection as high priority

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03472417

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.04.00

Version Found: BSA0106_NIGHTLY_2015-07-13

Version(s) Released: BSA0107_00.04.00

Headline:

Create an API to make connection as high priority

Release Note:

Created an API to make connection as high priority

BLTH03472914

Subsystem: avk

Version Found: N/A

Version(s) Released: BSA0107_00.05.00

Version Found: BSA01062_01.05.00

Version(s) Released: BSA0107_00.05.00

Headline:

BSA_AVK_STOP_EVT is recieved when 6 => AVK Start option chosen in app_avk

Release Note:

AVK start and stop methods are obsolete. The AV whitepaper recommendation is that only AV source starts and stops the stream. The AV sink should use AVRCP pass thru commands play and stop. The menu is removed.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03473487

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.23.00

Version Found: BSA0106_NIGHTLY_2015-07-22

Version(s) Released: BSA01062_01.23.00

Headline:

Add check routine for BSA command size

Release Note:

Add check routine for BSA command size.

BLTH03473488

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.05.00

Version Found: BSA0106_NIGHTLY_2015-07-22

Version(s) Released: BSA0107_00.05.00

Headline:

Add check routine for BSA command size

Release Note:

Add check routine for BSA command size.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03475490

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.06.00

Version Found: BSA0106_NIGHTLY_2015-07-31

Version(s) Released: BSA0107_00.06.00

Headline:

Create a android makefile for simple_app application

Release Note:

New android.mk file was added on customer project for simple_app application

BLTH03475491

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.24.00

Version Found: BSA0106_NIGHTLY_2015-07-31

Version(s) Released: BSA01062_01.24.00

Headline:

Create a android makefile for simple_app application

Release Note:

New android.mk file was added on customer project for simple_app application

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Major

BLTH03475673

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.06.00

Version Found: BSA0107_00.05.00

Version(s) Released: BSA0107_00.06.00

Headline:

app_av and app_avk does not work simutaneously

Release Note:

Enable app_av and app_avk simultaneous operation. Added method to add BSA server trace.

BLTH03476045

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.06.00

Version Found: BSA0106_NIGHTLY_2015-08-07

Version(s) Released: BSA0107_00.06.00

Headline:

Enable BTU_HANDLE_RAW_HCI_ENABLED definition on customer project

Release Note:

Enable BTU_HANDLE_RAW_HCI_ENABLED definition on customer project

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03444979

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.01.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA0107_00.01.00

Headline:

Merge BTE 323 AV code

Release Note:

Merge BTE 323 AV code

BLTH03445891

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.01.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA0107_00.01.00

Headline:

Merge BTE 323 AV code

Release Note:

Merge BTE 323 AV code

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects	Minor
-------------------------	--------------

BLTH03446939	Subsystem: BSA
Version Found:	N/A
Version(s) Released:	BSA0107_00.01.00
Version Found:	BSA0106_01.30.00
Version(s) Released:	BSA0107_00.01.00
Headline:	
AVRCP meta data fixes for BSA 107	
Release Note:	
AVK fixes	

BLTH03447391	Subsystem: BSA
Version Found:	N/A
Version(s) Released:	BSA01062_01.01.00
Version Found:	BSA0106_01.30.00
Version(s) Released:	BSA01062_01.01.00
Headline:	
Merge BTE 323 AV code	
Release Note:	
Merge BTE 323	

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03448106

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.01.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA01062_01.01.00

Headline:

Add SCM config file

Release Note:

Added SCM config file

BLTH03450657

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.03.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA01062_01.03.00

Headline:

Merge tip of BSA 106 CRs

Release Note:

Merge changes from BSA 106.1

All changes up to BSA0106_01.46.00 are merged

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03452461

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.04.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA01062_01.04.00

Headline:

Merge BSA 106.1 changes

Release Note:

Merge BSA 106.1 changes

BLTH03452939

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.04.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA01062_01.04.00

Headline:

Merge changes from BSA 106.1

Release Note:

Merge changes from 106.1]

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03460704

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.53.00

Version Found: BSA0106_NIGHTLY_2015-04-16

Version(s) Released: BSA0106_01.53.00

Headline:

Change delay time for HID audio streaming resolution from ms to us

Release Note:

Change delay time resolution of HID audio streaming

BLTH03460995

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.07.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA01062_01.07.00

Headline:

Merge changes from 106 branch

Release Note:

Merge changes from 106.1

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03461151

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.02.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA0107_00.02.00

Headline:

merge BSA 106.2 changes

Release Note:

merge BSA 106.2 changes

BLTH03461451

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.07.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA01062_01.07.00

Headline:

Fix compile

Release Note:

fixed compile issue

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects	Minor
-------------------------	--------------

BLTH03461464	Subsystem: BSA
Version Found:	N/A
Version(s) Released:	BSA0106_01.53.00
Version Found:	BSA0106_01.30.00
Version(s) Released:	BSA0106_01.53.00
Headline:	
Mark BSA specific code	
Release Note:	
Mark BSA specific code with comment /* BSA_SPECIFIC */ to distinguish changes from BTE	

BLTH03461725	Subsystem: BSA
Version Found:	N/A
Version(s) Released:	BSA01062_01.08.00
Version Found:	BSA0106_01.30.00
Version(s) Released:	BSA01062_01.08.00
Headline:	
Mark BSA specific code	
Release Note:	
Mark BSA specific code	

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects	Minor
------------------	-------

BLTH03461741	Subsystem: BSA
Version Found:	N/A
Version(s) Released:	BSA0106_01.53.00
Version Found:	BSA0106_01.30.00
Version(s) Released:	BSA0106_01.53.00
Headline:	
Fix compile error	
Release Note:	
Fix compile error	

BLTH03461745	Subsystem: BSA
Version Found:	N/A
Version(s) Released:	BSA01062_01.08.00
Version Found:	BSA0106_01.30.00
Version(s) Released:	BSA01062_01.08.00
Headline:	
Update AV and AVK to BTE 3.23	
Release Note:	
Updated to latest	

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03461752

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.02.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA0107_00.02.00

Headline:

BTE 323 stack update

Release Note:

Updated

BLTH03461856

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.02.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA0107_00.02.00

Headline:

BTE 323 stack update

Release Note:

Merge from bte323

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03462013

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.53.00

Version Found: BSA0106_NIGHTLY_2015-05-01

Version(s) Released: BSA0106_01.53.00

Headline:

Specify BLE Local key file with bsa_server command line option '-k'

Release Note:

Specify BLE Local key file with bsa_server command line option '-k'

BLTH03462015

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.53.00

Version Found: BSA0106_NIGHTLY_2015-05-01

Version(s) Released: BSA0106_01.53.00

Headline:

Changed BLE IO capability for customer proejct to NoInputNoOutput

Release Note:

Changed BLE IO capability for customer project to NoInputNoOutput

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03462017

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.53.00

Version Found: BSA0106_NIGHTLY_2015-05-01

Version(s) Released: BSA0106_01.53.00

Headline:

Enable BLE privacy feature for customer project

Release Note:

Enable BLE privacy feature for customer project

BLTH03462021

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.53.00

Version Found: BSA0106_NIGHTLY_2015-05-03

Version(s) Released: BSA0106_01.53.00

Headline:

Disable BLE local privacy for customer project

Release Note:

Disable BLE local privacy for customer project

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03462023

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.53.00

Version Found: BSA0106_NIGHTLY_2015-05-03

Version(s) Released: BSA0106_01.53.00

Headline:

Enable AV/AVK for customer project

Release Note:

Enable AV/AVK for customer project

BLTH03462219

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.02.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA0107_00.02.00

Headline:

Fix compile and merge issues

Release Note:

BTE 323 updates

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03462245

Subsystem: BTA HF

Version Found: N/A

Version(s) Released: BSA0106_01.53.00

Version Found: BTE0323_NIGHTLY_2015-05-01

Version(s) Released: BSA0106_01.53.00

Headline:

[BTE0323]Need to add 2_ev3 packet type in the default sco packet type in HS side

Release Note:

Added 2_ev3 packet type in the default sco packet type in HS side

BLTH03462334

Subsystem: BTA HF

Version Found: N/A

Version(s) Released: BSA01062_01.08.00

Version Found: BTE0323_NIGHTLY_2015-05-01

Version(s) Released: BSA01062_01.08.00

Headline:

[BTE0323]Need to add 2_ev3 packet type in the default sco packet type in HS side

Release Note:

Added 2_ev3 packet type in the default sco packet type in HS side

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03462856

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.10.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA01062_01.10.00

Headline:

Compile error in nuclues

Release Note:

Fix build issue

BLTH03462943

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.10.00

Version Found: BSA01062_01.10.00

Version(s) Released: BSA01062_01.10.00

Headline:

BSA01062- Fix Build issues

Release Note:

Resolved build issues

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03463150

Subsystem: BLE

Version Found: N/A

Version(s) Released: BSA0106_01.54.00

Version Found: BSA0106_01.48.00

Version(s) Released: BSA0106_01.54.00

Headline:

Not able to add 128-bit Service UUID to BLE Advertisement Data

Release Note:

Fixed the sol_services_128b w/in the tBSA_DM_BLE_ADV_CONFIG structure to be a data element vs a pointer.
Also added support for services_128b in the same structure and BSA DM component.

BLTH03463437

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.13.00

Version Found: BSA01062_01.03.00

Version(s) Released: BSA01062_01.13.00

Headline:

Customer request for adding decoding of Rx Test statistics in logging

Release Note:

Added decoding of the received rx test statistics(HCI_BRCM_VSE_SUBCODE_CONNECTIONLESS_RX_TEST_STATISTICS) in hcidisp.c

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03464105

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.03.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA0107_00.03.00

Headline:

LE secure connection

Release Note:

LE secure connection support.

BLTH03464107

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.06.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA0107_00.06.00

Headline:

Data packet extentions

Release Note:

Added LE Data Length Extension support.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03464184

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.54.00

Version Found: BSA0106_NIGHTLY_2015-05-20

Version(s) Released: BSA0106_01.54.00

Headline:

libbsa.txt update for media hub project

Release Note:

libbsa.txt update for media hub project
Add HID_DEV_MTU_SIZE = 800
add other BSA feature define

BLTH03464992

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.54.00

Version Found: BSA0106_NIGHTLY_2015-05-25

Version(s) Released: BSA0106_01.54.00

Headline:

Disable sniff substrate feature for customer platform.

Release Note:

Add BTM_SSR_INCLUDED = FALSE on customer bsa_server.txt file.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03465788

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.13.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA01062_01.13.00

Headline:

3 AVK connections - iPhone meta data is not displayed when connected from iPhone

Release Note:

Fixed meta data issue

BLTH03466480

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.54.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA0106_01.54.00

Headline:

Merge BSA 106.2 changes

Release Note:

Port changes from BSA 106.2

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03467196

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.20.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA01062_01.20.00

Headline:

Support for AVRCP absolute volume

Release Note:

Added support for absolute volume

BLTH03467297

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.58.00

Version Found: BSA0106_NIGHTLY_2015-03-22

Version(s) Released: BSA0106_01.58.00

Headline:

Add HOGP feature on STB project

Release Note:

New project has added as 'han_hogp' because many changes need to be done and the other new feature also implemented.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03467543

Subsystem: A2DP

Version Found: N/A

Version(s) Released: BSA0106_01.57.00

Version Found: BSA0106_NIGHTLY_2015-06-04

Version(s) Released: BSA0106_01.57.00

Headline:

Disable A2DP sink custom codec at customer project setting.

Release Note:

remove BSA_AVK_SEC_SUPPORT definition in customer bsa_server.txt

BLTH03467685

Subsystem: BLE

Version Found: N/A

Version(s) Released: BSA0106_01.57.00

Version Found: BSA0106_NIGHTLY_2015-06-10

Version(s) Released: BSA0106_01.57.00

Headline:

Associate BSA_BLE_CL_NV_LOAD_MAX and BTA_GATTC_NV_LOAD_MAX

Release Note:

Associate BSA_BLE_CL_NV_LOAD_MAX and BTA_GATTC_NV_LOAD_MAX.
These two definition should have the same value.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03467700

Subsystem: BLE

Version Found: N/A

Version(s) Released: BSA01062_01.18.00

Version Found: BSA0106_NIGHTLY_2015-06-10

Version(s) Released: BSA01062_01.18.00

Headline:

Associate BSA_BLE_CL_NV_LOAD_MAX and BTA_GATTC_NV_LOAD_MAX

Release Note:

Associate BSA_BLE_CL_NV_LOAD_MAX and BTA_GATTC_NV_LOAD_MAX.
These two definition should have the same value.

BLTH03467723

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.57.00

Version Found: BSA0106_NIGHTLY_2015-06-10

Version(s) Released: BSA0106_01.57.00

Headline:

Create a customer project

Release Note:

Create a customer project

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03469023

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.57.00

Version Found: BSA0106_NIGHTLY_2015-06-21

Version(s) Released: BSA0106_01.57.00

Headline:

Added the prototype declaration of BSA_ReadRemoteName

Release Note:

Added the prototype declaration of BSA_ReadRemoteName

BLTH03469186

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.57.00

Version Found: BSA0106_NIGHTLY_2015-06-21

Version(s) Released: BSA0106_01.57.00

Headline:

Fix compile error in customer application.

Release Note:

Fix compile error in customer application.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03469382

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.57.00

Version Found: BSA0106_NIGHTLY_2015-06-22

Version(s) Released: BSA0106_01.57.00

Headline:

Fix compile error in customer application.

Release Note:

Fix compile error in customer application.

BLTH03469964

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.58.00

Version Found: BSA0106_NIGHTLY_2015-06-25

Version(s) Released: BSA0106_01.58.00

Headline:

Remove unnecessary definition on Makefile in customer project folders

Release Note:

Removed BSA_ANDROID definition on customer project

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03470500

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.21.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA01062_01.21.00

Headline:

Absolute volume fixes

Release Note:

Fixes for abs volume. Added UI for showing vol percentage.

BLTH03470668

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.03.00

Version Found: BSA0106_01.30.00

Version(s) Released: BSA0107_00.03.00

Headline:

Update to latest BTE323

Release Note:

Update to BTE323

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects	Minor
-------------------------	--------------

BLTH03471002	Subsystem: BSA
Version Found:	N/A
Version(s) Released:	BSA01062_01.22.00
Version Found:	BSA0106_01.30.00
Version(s) Released:	BSA01062_01.22.00
Headline:	
	Update from BSA 106 branch
Release Note:	
	Updated from BSA (106.1) branch

BLTH03471625	Subsystem: BSA
Version Found:	N/A
Version(s) Released:	BSA0107_00.03.00
Version Found:	BSA0106_01.30.00
Version(s) Released:	BSA0107_00.03.00
Headline:	
	Fix compile issues
Release Note:	
	Fixed compile issues

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03471775

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.58.00

Version Found: BSA0106_NIGHTLY_2015-07-09

Version(s) Released: BSA0106_01.58.00

Headline:

Add bd address on tBSA_AVK_RC_OPEN_MSG struct

Release Note:

Add bd address on tBSA_AVK_RC_OPEN_MSG struct

BLTH03473973

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.23.00

Version Found: BSA0106_NIGHTLY_2015-07-26

Version(s) Released: BSA01062_01.23.00

Headline:

fix customer 20733 hid RCU OTA failure case

Release Note:

Remove check vs_location, vs_length routine since it is useless.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03473974

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0107_00.05.00

Version Found: BSA0106_NIGHTLY_2015-07-26

Version(s) Released: BSA0107_00.05.00

Headline:

fix customer 20733 hid RCU OTA failure case

Release Note:

Remove check vs_location, vs_length routine since it is useless.

BLTH03473978

Subsystem: GKI

Version Found: N/A

Version(s) Released: BSA01062_01.23.00

Version Found: BSA01062_01.22.00

Version(s) Released: BSA01062_01.23.00

Headline:

Typographical error when using NUCLEUS_BASE_PRIORITY

Release Note:

change from ifndef to ifdef.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Minor

BLTH03473980

Subsystem: GKI

Version Found: N/A

Version(s) Released: BSA0107_00.05.00

Version Found: BSA0107_00.04.00

Version(s) Released: BSA0107_00.05.00

Headline:

Typographical error when using NUCLEUS_BASE_PRIORITY

Release Note:

change from ifndef to ifdef.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Cosmetic

BLTH03465232

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.54.00

Version Found: BSA0106_NIGHTLY_2015-05-26

Version(s) Released: BSA0106_01.54.00

Headline:

Add BSA_SPECIFIC comment on chrisle_BLTH03460931 modification

Release Note:

Add BSA_SPECIFIC comment on chrisle_BLTH03460931 modification

BLTH03466630

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.55.00

Version Found: BSA0106_NIGHTLY_2015-06-03

Version(s) Released: BSA0106_01.55.00

Headline:

make clear display message for num of handle when a new service created.

Release Note:

make clear display message for num of handle when a new service created.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Cosmetic

BLTH03466637

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA01062_01.16.00

Version Found: BSA0106_NIGHTLY_2015-06-03

Version(s) Released: BSA01062_01.16.00

Headline:

make clear display message for num of handle when a new service created.

Release Note:

make clear display message for num of handle when a new service created.

BLTH03467547

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.57.00

Version Found: BSA0106_NIGHTLY_2015-06-04

Version(s) Released: BSA0106_01.57.00

Headline:

Add mediahub project to scm script

Release Note:

Modified scm build script

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Enhancements

BLTH03447203

Subsystem: Stack

Version Found:

N/A

Version(s) Released:

BSA0107_00.01.00

Version Found:

BSA0107_00.00.00

Version(s) Released:

BSA0107_00.01.00

Headline:

Port BTE0323

Release Note:

Ported BTE0323 and implemented HFP 1.7 in BSA.

BLTH03455242

Subsystem: BTA AVK

Version Found:

N/A

Version(s) Released:

BSA01062_01.05.00

Version Found:

BTE0323_NIGHTLY_2015-03-11

Version(s) Released:

BSA01062_01.05.00

Headline:

BTE0323 BTA AVK handle signaling open fail case in the AVK init state

Release Note:

BTA AVK handle signaling open fail case in the AVK init state

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Enhancements

BLTH03463311

Subsystem: BTE

Version Found: N/A

Version(s) Released: BSA0106_01.54.00

Version Found: BSA0106_01.53.00

Version(s) Released: BSA0106_01.54.00

Headline:

BTA_AVK_AV_AUDIO_RELAY code should depend on BTA_AVK_INCLUDED

Release Note:

The code will be include only when BTA_AVK_INCLUDED = TRUE

BLTH03463356

Subsystem: BTE

Version Found: N/A

Version(s) Released: BSA0106_01.54.00

Version Found: BSA0106_01.53.00

Version(s) Released: BSA0106_01.54.00

Headline:

To avoid an useless upgrade UART baud rate action

Release Note:

The upgrade UART baud rate for download patchram should only do once.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Enhancements

BLTH03463399

Subsystem: BTE

Version Found: N/A

Version(s) Released: BSA0106_01.54.00

Version Found: BSA0106_01.53.00

Version(s) Released: BSA0106_01.54.00

Headline:

Display OpCode correctly in simple_app

Release Note:

Should reverse OpCode formate then print it out.

BLTH03463595

Subsystem: BTE

Version Found: N/A

Version(s) Released: BSA0106_01.54.00

Version Found: BSA0106_01.53.00

Version(s) Released: BSA0106_01.54.00

Headline:

Correct return BSA Error status value

Release Note:

Change to the correct Error Status value.

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects	Enhancements
------------------	--------------

BLTH03464125

Subsystem: BSA

Version Found: N/A

Version(s) Released: BSA0106_01.54.00

Version Found: BSA0106_NIGHTLY_2015-05-18

Version(s) Released: BSA0106_01.54.00

Headline:

[BSA] BSA port for Android Lollipop

Release Note:

Modified BSA to build for Android OS.

BLTH03466752

Subsystem: AVRCP

Version Found: N/A

Version(s) Released: BSA0106_01.57.00

Version Found: BSA0106_01.54.00

Version(s) Released: BSA0106_01.57.00

Headline:

AVRCP Browsing Data error on 64bit linux machine

Release Note:

fix corrected byte alignment

Release notes from BSA 1.6.1.53 thru BSA 1.7.0.6

Resolved Defects

Enhancements

BLTH03470546

Subsystem: AVRCP

Version Found: N/A

Version(s) Released: BSA01062_01.22.00

Version Found: BSA01062_01.20.00

Version(s) Released: BSA01062_01.22.00

Headline:

AVRC locked on pending state.

Release Note:

send next command when received response packet.
