


## E ELECTRICAL WIRING ROUTING

### Position of Parts in Instrument Panel

[RHD]



\* 3:A/T  
 \* 5:M/T Bench Seat  
 \* 6:M/T Separate Seat  
 \*18:1HZ

J 1 Junction Connector  
 J 3 Junction Connector  
 J 4 Junction Connector  
 J 5 Junction Connector  
 J 6 Junction Connector  
 J 7 Junction Connector  
 J 8 Junction Connector  
 J 9 Junction Connector  
 J 10 Junction Connector  
 J 11 Junction Connector  
 J 12 Junction Connector  
 J 13 Junction Connector  
 J 14 Junction Connector  
 J 15 Junction Connector  
 J 16 Junction Connector  
 J 17 Junction Connector  
 J 19 Junction Connector

J 21 Junction Connector  
 J 22 Junction Connector  
 J 24 Junction Connector  
 J 25 Junction Connector  
 J 26 Junction Connector  
 J 27 Junction Connector  
 J 28 Junction Connector  
 J 29 Junction Connector  
 J 30 Junction Connector

K 3 Key Interlock Solenoid

M 4 Multi-Display  
 M 5 Multi-Display

P 3 Power Outlet (Front)  
 P 6 Pre-Heating Timer