

**ADDITIONAL NOTES TO THE MPI IN-LINE CAMERA SURVEY
MEDICAL CENTER SEWER LINE
(Appendix D and Figure 8, *Water Quality Investigation Report*, November 3, 2011)**

Run #1 - Starts at MC-2 and moves toward MC-3

Notes: (1) Good example of joint seepage at 30-ft. mark.

(2) Gravel debris at end of run.

Run #2 - Starts at MC-3 and moves toward MC-4

Run #3 - Starts at MC-2 and moves toward MC-1

Notes: (1) Observed infiltration at end of run that will require additional investigation.