




Adapter_Counterbore Hole 1




Adapter_Counterbore Hole 2




Adapter_Counterbore Hole 3




Adapter_Counterbore Hole 4




Adapter_Counterbore Hole 5




Adapter_Counterbore Hole 6



Adapter_Counterbore Hole 7



Adapter_Counterbore Hole 8



Batch Date: Received 8/24 (EPEC)

Yield Percentage: 96.67

Summary of Failed Boards: