



**KVP Health Care Inc.**  
**Biñan, Laguna**

Service Done

Date: 01 January 2023 - 31 January 2023

Client Name	Address	Machine	Reported Problem	Diagnosis	Work Done	Recommendation	Date of Service	Serviced By
SILANG SPECIALIST MEDICAL CENTER	Silang, Cavite	ULTRASOUND MACHINE - MEDISON / SONOACE R5	PRINTER NOT PROPERLY WORKING		DELIVER AND INSTALLED BNC CABLE FOR PRINTER., PERFORMED IMAGE TEST AND PRINT.OK	SYSTEM RUNNING	2023-01-03	DR
QUEEN MARY HOSPITAL	Ibaan, Batangas	CT SCAN MACHINE - GE / HISPEED DUAL	XG ERROR PHASE 4. 60-0313H EXPOSURE ERROR: ILR CURRENT DETECTED		PERFORMED PHYSICAL INSPECTION & WE NOTICED THAT THE XRAY TUBE HAS AN OIL. LEAK., REMOVE THE HV CABLES FROM HV TANK TO ISOLATE	SYSTEM DOWN., RECOMMEND XRAY TUBE REPLACEMENT.	2023-01-02	CJD

TUBE &  
PERFORMED  
NO LOAD  
TEST.  
RESULT:  
PASS.,  
RESTORE HV  
CABLE TO HV  
TANK &  
PERFORMED  
NO LOAD  
TEST AGIN,  
RESULT: ILR  
CURRENT  
ERROR.,  
DISMANTLE  
THE XRAY  
INSPECTION,  
NOTICE  
ALSO AIR  
BUBBLES  
INSIDE.,  
XRAY TUBE  
UNIT IS  
DEFECTIVE.

QUEEN MARY HOSPITAL	Ibaan, Batangas	CT SCAN MACHINE - GE / HISPEED DUAL	XG ERROR PHASE 4, 60-0313H EXPOSURE ERROR: ILR CURRENT DETECTED., DELIVERY AND INSTALLATIO N OF XRAY	DELIVERY AND INSTALLATIO N OF XRAY TUBE INSERT S?N : 102914HU9., PERFORMED TUBE WARM UP AND WATER	SYSTEM RUNNING AND READY TO USE.	2023-01-05	CDR
---------------------------	--------------------	---	--	---	---	------------	-----

TUBE.

PHANTOM  
TEST.OK.,  
CLEARANCE  
BETWEEN  
ROTATIONAL  
AND  
STATIONARY  
COMPONENT  
S.OK., XRAY  
ALIGNMENT  
CHECK.OK.,  
KV AND MA  
CHECK.OK.,  
DAS COUNT  
CHECK.OK.,  
SYSTEM CALI  
BRATION.OK.  
, IMAGE PER  
FORMANCE  
CHECK.OK.

ROGACIANO Sta.Maria,  
M. MERCADO Bulacan  
MEMORIAL  
HOSPITAL

GENERAL  
XRAY  
MACHINE - jpi  
/ DRE 500ma

UNEXPECTE  
D ERROR  
DURING  
EXPOSURE.,  
TOO LONG  
COOL  
WAITING  
AFTER  
ERROR IS  
OCCURED

UPON  
CHECKING  
OF THE  
EXPOSURE,  
FOUND OUT  
THAT SOME  
EXPOSURE  
TIME IS  
LONGEST  
THAN THE  
SELECTED  
EXPOSURE  
TIME  
FACTORING.,  
\* NEED FOR  
RECALIBRATI

SYSTEM IS  
RUNNING.,  
OBSERVE MA  
NDATORYEX  
POSURE  
LIMITS  
WHICH IS  
LESS THAN  
100  
EXPOSURES  
PER DAY  
BASE ON  
MACHINE  
OLD AGE.,  
NEED RECAL  
IBRATIONOF

2023-01-05

JAS

ON TO AVOID THE XRAY  
 THE UNIT AND  
 UNEXPECTE REPAIR OF  
 D ERROR TUBE  
 OCCUR., COLUMN  
 ALSO THE ASSEMBLY.  
 TUBE  
 COLUMN IS  
 MIASLIGNED  
 DUE TO  
 BROKEN  
 TRANSPORT  
 BEARINGS\*  
 NEED FOR R  
 EPLACEMEN  
 T AND REALI  
 GNMENT.,  
 THE CR  
 SYSTEM IS  
 NEED A  
 MADATORY  
 HARDWARE  
 CLEANING  
 TO AVOID  
 ROLLER  
 MARKS AT  
 THE IP  
 CASSETTE  
 THAT MAY  
 CAUSE FOR  
 PERMANENT  
 DAMAGE.

TEKNOMED DIAGNOSTIC CENTER	Quezon City	CR SYSTEM MACHINE - FUJI / PRIMA T2	CASSETTE STUCK UP AT CR SYSTEM	PERFORMED EXPOSURE AND IMAGE TEST.,	SYSTEM RUNNING AND READY TO USE., AS	2023-01-10	RICHARD/JU NEVIN
----------------------------------	-------------	--	--------------------------------------	--	---	------------	---------------------

COMPLETED THE PATIENT DETAILS AND COMPLETED THE SCANNING BEFORE INSERTING AND EJECTING THE CASSETTE FROM CR SYSTEM., PERFORMED SCANNING SEVERAL TIMES AND NO ERROR ENCOUNTERED.

TEKNOMED DIAGNOSTIC CENTER	Quezon City	CR SYSTEM MACHINE - Fuji / Prima T2	CASSTTE STUCK UP AT CR SYSTEM	PERFORMED EXPOSURE & IMAGE TEST., COMPLETED THE PATIENT DETAILS & COMPLETED THE SCANNING BEFORE INSERTING & EJECTING THE CASSETTE FROM CR	SYSTEM RUNNING & READY TO USE., AS OBSERVED ERROR ENC OUNTERED DUE TO MISHANDLIN G OF THE EQUIPMENT BY THE CLIENT TECHINICIAN .	2023-01-10	RICHARD/ JUNEVIN
----------------------------------	-------------	---	-------------------------------------	---	---	------------	---------------------

					SYSTEM., PERFORMED SCANNING SEVERAL TIMES & NO ERROR ENC OUNTERED			
TEKNOMED DIAGNOSTIC CENTER	Quezon City	GENERAL XRAY MACHINE - Ge / KX-21/300ma			CHECKED ALL WIRING CONNECTIO NS.OK.,CHEC KED THE MECHANICAL MOVEMENTS OF THE TUBE ROTATION & TUBE STAND., PERFORMED EXPOSURE & IMAGE TEST., OK.,PERFOR MED INTERIOR & EXTERIOR MACHINE CLEANING.,	SYSTEM RUNNINGAN D READY TO USE.	2023-01-10	RICHARD / JUNEVIN
HOLY ROSARY OF CABUYAO HOSPITAL	Cabuyao, Laguna	MAMMOGRA PHY MACHINE - GENORAY / DNX600	BOOT UP PROBLEM (BLACK SCREEN DISPLAY)	HOST COMPUTER PROBLEM	*REPLACED HOST COMPUTER *PERFORME D SYSTEM C ONFIGURATI ON *PERFORME D DETECTOR	THE MACHINE IS FULLY FUNCTIONAL AND READY TO USE.	2023-01-12	JR

CALIBRATION - OK  
 \*PERFORMED AIR CALIBRATION - OK  
 \*PERFORMED ROTOR AND EXPOSURE TEST - OK  
 \*PERFORMED ACTUAL SCANNING - OK  
 \*PERFORMED IMAGE QUALITY CHECK - OK

LUZON MEDICAL CENTER	DAGUPAN, PANGASINAN	CT SCAN MACHINE - GE / LIGHTSPEED	Installation Completion.	Power on and verify control boot up sequence. Performed Flash Download all system nodes. okay. Performed Gantry Table Alignment. Performed System Calibration. Performed scan water	System Running and ready for application training.	2023-01-11	Aldrin, Cloyd, Jeff, Dred
----------------------	---------------------	-----------------------------------	--------------------------	---	--	------------	---------------------------

phantom and scan volunteer patient. Check image quality okay. Performed savestate. okay. Performed installation of workstation, dicom transfer. okay Performed installation of PC computer and printer. Test Print. Okay.

SAINT  
PASCAL DE  
BAYLON  
HOSPITAL

San Pascual,  
Batangas

CT SCAN  
UPS - INV T /  
HT33060X

VOID

2023-01-13

CLOYD

ST. JOHN  
THE BAPTIST  
MEDICAL  
CENTER

Calamba,  
Laguna

CT SCAN  
MACHINE -  
GE /  
LIGHTSPEED

DELIVERY &  
INSTALLATIO  
N

January 3,  
2023 Delivery  
and  
Installation.  
Power on.  
LFC. Flash  
Download  
DCB Error.  
Also, noticed  
that the  
HEMRC Board  
has GFLT Red  
Light Error.

Recommend  
replacement of  
DCB, HEMRC  
&/or CCB  
Board.

2023-01-03

Aldrin, Jeff,  
Cloyd, Dred



LUZON MEDICAL CENTER	DAGUPAN PANGASINAN	CR SYSTEM MACHINE - JPI / EXAMVUE PRO	INSTALLATI ON COMPLETION	INSTALLATIO N OF CT SCAN WAS COMPLETED. , POWER ON AND VERIFY CONTROL BOOT-UP SEQUENCE., PERFORMED FLASH DOWNLOAD ALL SYSTEM MODES.OK., PERFORMED GANTRY, TABLE ALIGN MENT.OK., PERFORMED SYSTEM CALI BRATION.OK.  , PERFORMED SCAN WATER PHANTOM AND SCAN VOLUNTEER PATIENT, CHECK IMAGE QUALITYT. OK., PERFORMED SAVE SYSTEM STATE.OK.,	SYSTEM RUNNING AND READY FOR APPLICATION TRAINING	2023-01-09	ACJD
----------------------------	-----------------------	---	--------------------------------	--	--	------------	------

					PERFORMED INSTALLATIO N OF WORKS TATION DICOM TRAN SFER.OK., PERFORMED INSTALLATIO N OF PC COMPUTER & PRINTER. TESTR PRINT.OK.			
HOLY ROSARY OF CABUYAO HOSPITAL	Cabuyao, Laguna	MAMMOGRA PHY MACHINE - DONGMUN / DMX600	BOOT -UP PROBLEM ( BLACK SCREEN DISPLAY)	HOST COMPUTER PROBLEM	REPLACED THE HOST COMPUTER., PERFORMED SYSTEM CON FIGURATION.	THE MACHINE IS FULLY FUNCTIONAL AND READY TO USE	2023-01-12	JR
					, PERFORMED DETECTOR C ALIBRATION. OK, PERFORMED AIR CALIBRA TION.OK, PERFORMED RPTPR AND EXPOSURE TEST.OKI, PERFORMED ACTUAL SCA NNING.OK, PERFORMED IMAGE			

					QUALITY CHECK.OK.			
GLOBAL CARE MEDICAL CENTER OF CANLUBANG	canlubang, laguna	GENERAL XRAY MACHINE - GE / XR 6000	Machine not functional.	Cables/ Wires were broken due to rat bite, dead rats found inside PDU. Due to sudden electrical surge caused by shorted circuits, xray tube was affected	Traced connectivity of all wires/cables. Restored connection of wires/cables broken by rats. Restored system connections. Troubleshoot as per machine maintenance manual.	Machine still not functional. Conduct further troubleshootin g upon availability of new xray tube.	2023-01-17	Aldrin, Cloyd, Jeff, Dave
SILANG SPECIALIST MEDICAL CENTER	Silang, Cavite	GENERAL XRAY MACHINE - LISTEM / REX 525R	Derailed Xray Tube Stand		Upon arrival of KVP Service Team at Silang Specialist Xray Room last Jan. 16, 2023, incedent details were requested from tech on duty. It was reported that the intern staff was operating the xray machine and after rotating	System Running.	2023-01-16	Jeff, Dred, Cloyd, Awin, Richard, Rogelio, Birbir

the tube stand  
and pulling the  
tube arm, the  
xray tube  
stand fell.  
Upon  
performing  
physical  
inspection, it  
was found out  
that the tube  
stand ceiling  
support was  
derailed from  
the railing with  
signs of force  
movements.  
KVP  
Performed  
replacement of  
xray tube  
stand ceiling  
railings. KVP  
Performed  
alignment

MEDICAL CENTER IMUS	Imus, Cavite	MAMMOGRA PHY MACHINE - ANKE / ASR-4000	IMAGE ARTIFACTS	PERFORMED INSPECTION. , AFTER INSPECTION, WE FOUND OIUT THAT THE MYLAR OF COLLIMATOR WAS DISALLI GNED.,	SYSTEM RUNNING	2023-01-18	DR
---------------------------	--------------	--	--------------------	---	-------------------	------------	----

PERFORMED  
DISMANTLE  
THE TUBE  
COLLIMATOR  
COVER AND  
ADJUST THE  
MYLAR.,  
PERFORMED  
INSTALLED  
THE TUBE  
COLLIMATOR  
COVER AND  
PERFORMED  
TESTING.OK.,  
PERFORMED  
EXPOSURE  
AGAIN AND  
CHECK  
IMAGE  
QUALITY BY  
RADTECH.OK

ST. JOHN THE BAPTIST MEDICAL CENTER	Calamba, Laguna	CT SCAN MACHINE - GE / LIGHTSPEED	INSTALLLATI ON COMPLETION	INSTALLATIO N OF CT SCAN WAS COMPLETED. , POWER ON AND VERIFY CONTROL BOOT-UP SEQUENCE., PERFORMED FLASH DOWNLOAD ALL SYSTEM NODES.OK., PERFORMED	SYSTEM RUNNING AND READY TO USE.	2023-01-11	CJD
--	--------------------	--	---------------------------------	---	---	------------	-----

GANTRY,  
TABLE ALIGN  
MENT.OK.,  
PERFORMED  
SYSTEM CALI  
BRATION.OK.

,  
PERFORMED  
SCAN  
WATER  
PHANTOM  
AND SCAN  
VOLUNTEER  
PATIENT,  
CHECK  
IMAGE  
QUALITY.OK.,  
PERFORMED  
SAVE  
SYSTEM  
STATE.OK.,  
PERFORMED  
INSTALLATIO  
N OF WORKS  
TATION  
DICOM TRAN  
SFER.OK.,  
PERFORMED  
I8NSTALLATI  
ON OF PC  
COMPUTER  
& PRINTER,  
TEST  
PRINT.OK.

GLOBAL CARE	canlubang, laguna	GENERAL XRAY	MACHINE NOT	CABLES / WIRES	TRACED CON NECTIVITY	MACHINE STILL NOT F	2023-01-17	CJA
----------------	----------------------	-----------------	----------------	-------------------	-------------------------	------------------------	------------	-----

MEDICAL CENTER OF CANLUBANG		MACHINE - GE / XR 6000	FUNCTIONAL	BROKEN DUE TO RAT BITE; DEAD RATS FOUND INSIDE PDU., DUE TO SUDDEN ELECTRICAL SURGE CAUSED BY SHORTED CIRCUITS, XRAY TUBE WAS AFFECTED.	OF ALL / CABLES., RESTORED C ONNECTION S OF WIRES/ CABLES BROKEN BY RATS., RESTORED SYSTEM CON NECTIONS., T ROUBLESHO OT AS PER MACHINE MA INTENANCE MANUAL.	UNCTIONING, CONDUCT FURTHER TR OUBLESHOO TING UPON AVAILABILTY OF NEW XRAY TUBE		
SILANG SPECIALIST MEDICAL CENTER	Silang, Cavite	GENERAL XRAY MACHINE - LISTEM / REX 125	DERAILED XRAY TUBE STAND		UPON ARRIVAL OF KVP SERVICE TEAM AT SILANG SPECIALIST XRAY ROOM LAST JAN 16, 2023 INCEDENT DETAILS WERE REQUESTED FROM TECH ON DUTY., IT WAS REPORTED THAT THE INTERN	SYSTEM RUNNING	2023-01-16	CJDR

STAFF WAS  
OPERATING  
THE XRAYT  
MACHINE,  
AND AFTER  
ROTATING  
THE TUBE  
STAND AND  
PULLING THE  
TUBE ARM,  
THE XRAY  
TUBE STAND  
FELL., UPON  
PERFORMIN  
G PHYSICAL  
INSPECTION  
IT WAS  
FOUND OUT  
THAT THE  
TUBE STAND  
CEILING  
SUPPORT  
WAS  
DERAILED  
FROM THE  
RAILINGS  
WITH SIGNS  
OF FORCED  
MOVEMENTS  
., KVP  
PERFORMED  
REPLACEME  
NT OF XRAY  
TUBE STAND  
CEILKING  
RAILINGS.,  
KV



ASSUMPTION SPECIALTY HOSPITAL AND MEDICAL CENTER	Antipolo	MRI MACHINE - HITACHI / AIRIES 2 (.3)	NOT WORKING QD FLEX BODY COIL		PERFORMED ALIGNMENT.  REPLACE AND INSTALLED QD FLEX BODY COIL., PERFORMED COIL SYSTEM CON FIGURATION. , PERFORMED TEST SCAN USING NEW QD FLEX BODY COIL WORKS NORMALLY., CHECK SNR OUTPUT, DONE.OK.	SYSTEM RUNNING AND READY TO USED., PLEASED OBSERVE WHILE IN KEEPING THE QD FLEX BODY COIL, NOT TO BEND	2023-01-16	JAS
MEDICAL CENTER IMUS	Imus, Cavite	MAMMOGRA PHY MACHINE - ANKE / ASR-4000E	IMAGE ARTIFACT	POSSIBLE PROBLEM : DETECTOR	PERFORMED DETECTOR CALIBRATIO N AND GAIN CALIBRATIO N, BUT WE E NCOUNTERED AN ERROR POSSIBLE CAUSE OF THE ERRORS IS THE DETECTOR.	WE NEED THE DEVICE CHECK DETECTOR TO CONFIRM IF THE DETECTOR IS CAUSING THE ERROR,	2023-01-19	DR

BALAYAN BAYVIEW HOSPITAL AND MEDICAL CENTER	Balayan, Batangas	CT SCAN MACHINE - Ge / Brightspeed 16 slice		PERFORMED MACHINE INSPECTION AND CONDITI ON.OK, CONDUCTED PREVENTIVE MAINTENANC E AND SERVICE., PERFORMED INTERIOR AND EXTERIOR MACHINE CLEANING., SYSTEM RUNNING.	2023-01-20	DRA
SAINT PASCAL DE BAYLON HOSPITAL	San Pascual, Batangas	CT SCAN MACHINE - Ge / BrightSpeed 16 Slice		CONDUCTED PMS., PERFORMED MT CART CL EANING.OK., PERFORMED PRINTING IMAGE.OK., CHECKED PRINTING INK LEVEL.OK	2023-01-20	DRA
MIRACULOU S FAITH ULTRASOUN D AND DIAGNOSTIC	Malolos, Bulacan	CT SCAN MACHINE - GE / HIGHSPEED CTE	RING ARTIFACTS., UNEXPECTE D STOP SCAN	PERFORMED REPLACEME NT AND INSTALLED LOW	2023-01-20	JAS
				SYSTEM IS RUNNING AND CALIBRATED. , READY FOR		

CENTER			DURING ROUTINE PR OCEDURES., PREVENTIVE MAINTENANC E SERVICE (PMS)	VOLTAGE POWER SUPPLY. DONE., CHECK OUTPUT VOLTAGE AFTER REPL ACEMENT AND INSTALL ATION., PERFORMED ROUTINE CALIBRATIO N, DONE SUC CESSFULLY., PERFORMED PHANTOM TEST SCANNING, DONE NO ARTIFACT IS NOTED.	ACTUAL PATIENT PR OCEDURES.		
ST. JOHN THE BAPTIST MEDICAL CENTER	Calamba, Laguna	CT SCAN MACHINE - GE / LIGHTSPEED			CONDUCT PREVENTIVE MAINTENANC E SERVICE., PERFORMED TUBE WARM AND PHANTOM TEST.OK., PERFORMED PROTOCOL MANAGMENT AND RECON	2023-01-23	ADR

			MANAGEMENT. T.O.K., PERFORMED INSTALL RED LIGHT WIRING CONNECTION. DONE., SYSTEM RUNNING		
SAN LORENZO RUIZ HOSPITAL	naic, cavite	GENERAL XRAY MACHINE - Allengers / MARS - 6R	CHECKED BOOT-UP SEQUENCE OF THE MACHINE., CHECKED ALL THE SELECTION BUTTONS AND FUNCTION. O.K., CHECKED THE MECHANICAL MOVEMENT OF THE MACHINE.O.K., PERFORMED ROTOR AND EXPOSURE TEST.O.K., PERFORMED PMS., PERFORMED MACHINE	2023-01-17	DR

			CLEANING INTERIOR AND EXTERIOR., SYSTEM RUNNING AND READY TO USE.		
SAN LORENZO RUIZ HOSPITAL	naic, cavite	CR SYSTEM MACHINE - Examvue / CR PRO	PMS CHECK AND INSPEC TION.OK., PERFORMED EXPOSURE TEST.OK., PERFORMED CLEANING.O K., ( CR SYSTEM- PMS)., CHECK ALL CASSETTES AND PERFORMED CLEANING.O K., CHERCK SCANNING P ROCESS.OK., CHECK IMAGE QUALITY.OK., SYSTEM RUNNING.	2023-01-17	DR
SAN LORENZO RUIZ HOSPITAL	naic, cavite	PORTABLE / MOBILE XRAY MACHINE -	CHECKED BOOT-UP SEQUENCE OF THE	2023-01-17	DR

Allengers /  
Mars - 6R

MACHINE.,  
CHECKED  
ALL THE  
SELECTION  
BUTTONS  
AND FUNCTI  
ON.OK.,  
CHECKED  
THE  
MECHANICAL  
MOVEMENT  
OF THE  
MACHINE.OK.

,  
PERFORMED  
ROTOR AND  
EXPOSURE  
TEST.OK.,  
PERFORMED  
PMS.,  
PERFORMED  
MACHINE  
CLEANING  
INTERIOR  
AND  
EXTERIOR.,  
SYSTEM  
RUNNING  
AND READY  
TO USE.

LUZON MEDICAL CENTER	DAGUPAN, PANGASINAN	CT SCAN MACHINE - GE / LIGHTSPEED	APPLICATION TRAINING., TURN OVER & WARRANTY CERTIFICATE	FUNCTIONAL / OPERATIONA L	INSTRUCT THEM TO MAINTAIN THE REQUIRED ROOM TEMP	SYSTEM RUNNING & READY TO USE., RECOMMEN D TO	2023-01-18	CJ
----------------------------	------------------------	--	--	------------------------------------	---	--	------------	----

ERATURE &	PURCHASE 2
HUMIDITY.,	UNITS OF DE
TEACH HOW	HUMUDUFIE
TO POWER	R ( AT LEAST
ON/OFF THE	20 LITERS
WHOLE	CAPACITY).,
SYSTEM,	APPS
BASIC TROU	SPECIALISTE
BLESHOOTIN	: RONZUELO
G., SHOW &	NACIONAL,/H
EXPLAIN THE	OSPITAL
FUNCTIONAL	RADTECHS:
WORKS OF	DENVER
GANTRY,	CAYETANO,
TABLE, PDU	JERREMY
& CONSOLE.,	JAVIER,
CONFIGURE	DANIEL
ALL	JEREMY
PROTOCOL	NAVARRO,
S NEEDED	REDENSON
INCLUDING	LORESCO &
VOICE	ARJIE
COMMAND.,,,	MAPALO.
SCAN 232	
VOLUNTER	
PATIENTS	
WITH	
PROCEDURE	
S LIKE	
BRAIN,	
CHECT,	
NECK,	
FACIAL	
WHOLE	
ABDOMEN,	
EXTREMITIE	
S,	

STONOGRAM  
 , PNS, ETC.  
 TRY  
 SIMULATE  
 CONTRAST  
 EXAM.,  
 DICOM  
 TRANSFER  
 OF PATIENT  
 EXAMINATIO  
 N FROM CT  
 SCAN TO WO  
 RKSTATION.,  
 LEARN  
 IMAGE POST  
 PROCESSIN  
 G  
 PROCEDURE  
 , SENDING  
 THRU EMAIL,  
 FILMING.,  
 PERFORMED  
 ALSO  
 SAVING TO  
 USB, CD &  
 EXTERNAL  
 HARD DISK.

CENTRO  
 MEDICO DE  
 SANTISIMO  
 ROSARIO

Balanga,  
 Bataan

CT SCAN  
 MACHINE -  
 Ge /  
 Revolution  
 ACT

PERFORMED  
 PREVENTIVE  
 MAINTENANC  
 E SERVICE.,  
 CHECKED  
 ALL  
 SELECTION  
 BUTTONS  
 AND FUNCTI

2023-01-25

ADR



CENTRO  
MEDICO DE  
SANTISIMO  
ROSARIO

Balanga,  
Bataan

GENERAL  
XRAY  
MACHINE -  
Fuji / smart fb

ONS.OK.,  
CHECKED  
MECHANICAL  
MOVEMENT  
OF PATIENR  
TABLE UP,  
DOWN AND  
MOVE  
IN/OUT.OK.,  
PERFORMED  
TUBE  
CLEANING.,  
SYSTEM  
RUNNING  
AND READY  
TO USE.

CHECKED  
ALL THE  
MECHANICAL  
MOVEMENT.  
OK.,  
CHECKED  
ALL  
SELECTION  
BUTTONS.OK

2023-01-25

ADR

,  
ADJUSTMEN  
T OF  
COLLIMATOR  
FOR  
ROTATION  
MOVEMENT.,  
ADJUSTMEN  
T OF  
COLLIMATOR  
WINDOW.,

				PERFORMED PMS AND MACHINE CLEANING., SYSTEM RUNNING AND READY TO USE., CONDUCT PMS OF CLEAR PRINTER., PERFORMED MT CART CLEANING AND TEST PRINT.OK.		
CENTRO MEDICO DE SANTISIMO ROSARIO	Balanga, Bataan	ENDOSCOPY MACHINE - Evis / Exera II		PERFORMED PMS., CHECKED BOOT UP SE QUENCE.OK., CHECKED AIR AND WATER OUTPUT.OK., SUCTION MACHINE TEST.OK., CLEANING OF PROCESSOR AND LIGHTH SOURCE., PERFORMED CAMERA	SYSTEM RUNNING AND READY TO USE.	2023-01-25      ADR

TEST.OK.

RT Lim Family Hospital	Rt Lim, Zamboanga Sibugay	CT SCAN MACHINE - ANKE / CLARITY 64			FDA PERFOR MANCE TEST ING.PASS., SYSTEM RUNNING AND READY TO USE., TUBE WARM UP & SCAN WATER PHANTOM IMAGE CHECK.OK., DICOM TRANSFER FROM CT TO WORKSTATI ON., TEST PRINTING.OK	2023-01-25	CJ
SILANG SPECIALIST MEDICAL CENTER	Silang, Cavite	CT SCAN MACHINE - GE / BRIVO CT 385	FIRMWARE RESET OCCURED DURING SCANNING	ANALYSING THE ERROR OCCURED DURING SCANNING AND PHYSICAL INSPECTION OF GANTRY., PERFORMED CLEANING OF SLIP RING, POWER AND SIGNAL BRUSH	SYSTEM RUNNING AND READY TO USE., UPON CHECKING THE BODY STRAP AND HEAD TRAP POSSIBLE NEED FOR R EPLACEMEN T.	2023-01-26	ADA

USING A  
SPECIAL  
ABRASIVE  
ERASER.,  
INSPECTION  
RESET AND  
RETIGHTNIN  
G OF CONNE  
CTORS.OK.,  
MEASURING  
HIGH AND  
LOW VOLTAG  
ES.OK.,  
CHECK  
ROOM TEMP  
ERATURE  
AND  
HUMIDITY  
CHECK.,  
FUNCTIONAL  
CHECK AND  
ADJUSTMEN  
T.OK.,  
PERFORMED  
TUBE WARM  
UP AND  
WATER  
PHANTOM  
TEST.,  
SYSTEM  
CALIBRATIO  
N, IMAGE  
CHECK AND  
CT NUMBER  
MEASUREME  
NTS.,  
CONDUCT

PREVENTIVE  
MAINTENANC  
E (PMS).

SOUTH IMUS SPECIALIST HOSPITAL	Imus, Cavite	GENERAL XRAY MACHINE - DRE 140 / JPI	CONDUCT PMS., PERFORMED CHECK ALL MECHANICAL MOVEMENT OF TABLE, TUBE STAND & BUCKY STAND.OK., PERFORMED CHECK ALL SELECTION BUTTONS, & CHECK COLLIMATOR BLADE WINDOW.OK. , PERFORMED EXPOSURE AND IMAGE TEST SOME CASSTTE HAVE LINE ARTIFACTS., PERFORMED CLEAN ALL C ASSETTES.O K., [ERFORMED AUTO ALLIGN MENT.OK.,	2023-01-26	DA
--------------------------------------	--------------	---	--	------------	----

SOUTH IMUS SPECIALIST HOSPITAL	Imus, Cavite	CR SYSTEM MACHINE - PERLOVE / PLX 101C	PERFORMED CALIBRATIO N.OK., PERFORMED EXPOSURE AND IMAGE TEST SEVERAL TIMES. OK.,SYSTEM RUNNING.		
			CONDUCT PMS., PERFORMED CHECK ALL MECHANICAL OF TABLE, TUBE & BUCKY STAND.OK., PERFORMED CHECK ALL SELECTION BUTTONS & CHECK COLLIMATOR OR BLADE WINDOW.OK. , PERFORMED EXPOSURE AND IMAGE TEST, SOME CASSETTE HAVE LINE ARTIFACTS.,	2023-01-26	DA

SOUTH IMUS  
SPECIALIST  
HOSPITAL

Imus, Cavite

PORTABLE /  
MOBILE  
XRAY  
MACHINE -  
PERLOVE /  
PLX 101C

PERFORMED  
CLEAN ALL C  
ASSETTES.O  
K.,  
PERFORMED  
AUTO ALLIGN  
MENT.OK.,  
PERFORMED  
CALIBRATIO  
N.OK.,  
PERFORMED  
EXPOSURE  
AND IMAGE  
TEST  
SEVERAL  
TIMES.OK  
SYSTEM  
RUNNING.

CONDUCT  
PMS.,  
PERFORMED  
CHECK ALL  
MECHANICAL  
MOVEMENT.  
OK.,  
PERFORMED  
CHECK  
WHEEL  
CASTER.OK.,  
PERFORMED  
CHECK ALL  
SELECTION  
BUTTONS &  
CHECK  
COLLIMATOR  
BLADE

2023-01-26

DA

						WINDOW.OK. , PERFORMED EXPOSURE AND IMAGE TEST.OK, SYSTEM RUNNING.		
LEONCIO HOSPITAL	BROOKES POINT PALAWAN	CT SCAN MACHINE - GE / HISPEED DUAL				SYSTEM RUNNING AND READY TO USE., CHECK THE ROOM TEMP ERATURE & HUMIDITY MONITORING CHART., TUBE WARM- UP SCAN WATER PHANTOM IMAGE CHECK. OK., CT NUMBER MEASUREME NT FROM CT CONSOLE TO PC DICOM VIEWER, TEST PRINT.OK	2023-01-26	CJ
CENTRO MEDICO DE SANTISIMO ROSARIO	Balanga, Bataan	PORTABLE / MOBILE XRAY MACHINE -	BROKEN WHEEL CASTER., DEFECTIVE	LOOSE POWER OUTLET CONNECTIO	PERFORMED PMS., CHECKED MECHANICAL	SYSTEM IS RUNNING	2023-01-25	ADR



Dongmun / Dm-525mr		DRIVING KEY AND EMERGENCY STOP BUTTON.	N THAT CAUSES DAMAGE TO CHARGER BOARD.	MOVEMENT. OK REPLACED 2 PIECES OF WHEEL CASTER., REPLACED DRIVING KEY AND EMERGENCY STOP BUTTON., PULLOUT SCREW FROM THE COLLIMATOR ., UPON POWER ON THE MACHINE, WE NOTICED THAT THE BATTERY CHARGER IS NOT WORKING WE FOUND OUT THAT THE CHARGER BOARD IS DAMAGED.			
CENTRO MEDICO DE SANTISIMO ROSARIO	Balanga, Bataan	PORTABLE / MOBILE XRAY MACHINE -	power charging is not working during system power	replace and installed the charger board assy, done.,	xray unit is system running and ready for	2023-01-28	JAS

DONGMUN / up  
DM 525MR

performed  
system power  
up, done ok.  
but suddenly  
cut off power  
from the  
hospital power  
line while  
attempting for  
test xray  
exposure.,  
wait for a  
minute to  
come back the  
hospital  
current.,  
performed,  
system power  
up again after  
return the  
hospital power  
current and  
test xray  
exposure for  
several times  
and different  
technical  
factors, works  
normally,

actual patient  
procedures.,  
pleased  
provide a  
uninterruptabl  
e power  
supply to  
avoid the  
suddenly  
observed  
current  
fluctuations  
that may  
cause for  
major xray  
problem.

CLINICA  
LAGUNA MUL  
TISPECIALTY  
CENTER AND  
DIAGNOSTIC  
S (CABUYAO)

Cabuyao,  
Laguna

GENERAL  
XRAY  
MACHINE -  
PICKER /  
PICKER

NO ROTOR &  
EXPOSURE

PERFORMED  
CLEANING  
OF MA  
SELECTOR  
CONTRACTS.  
, CHECK  
ROTOR OPE

SYSTEM  
RUNNING &  
READY TO  
USE

2023-01-30

CJD

RATION.OK.,  
CHECK EXPO  
SURE.OK.