

# SUPRA QUALITY EXPORTS (I) PVT LTD

A-92, Road No. 16,  
Wagle Industrial Estate  
Thane west-400604  
India

S/DIR/34 Rev.12 26/08/25  
Phone : 45196493/94/95/96  
Email: quality@supraexports.in

## DIMENSIONAL INSPECTION REPORT

Part Description:- **MS TERMINAL**

Part No:- **04-1040**

C.P.O:-

Order Date:-

Order Qty:-

Vendor Name:- **Bijoy**

S.P.O: SQPO252610306

Order Date:- **11-09-2025**

Order Qty:- **21000**

Buyer name:- **THERMOGLOW** DATE:- **24-9-2025**

Report No:- **2526/0091**

ZINC	<input type="checkbox"/>
COPPER	<input type="checkbox"/>
NICKEL	<input type="checkbox"/>
NICKEL CHROME	<input type="checkbox"/>
TIN	<input type="checkbox"/>
Un-plated	<input type="checkbox"/>

### MATERIAL GRADE :-

SR NO	SAMPLE PARAMETER	1	2	3	4	5	6	7	8	9	10	REMARK
1	$9.25 \pm 0.2$	9.20	9.27	9.40	9.23	9.22	9.23	9.29	9.22	9.20	9.23	OK
2	$8.85 \pm 0.2$	8.90	8.90	8.97	8.95	8.95	8.92	8.90	8.93	8.89	8.94	OK
3	$4.00 \pm 0.1$	4.06	4.11	4.21	4.14	4.08	4.04	4.07	4.10	4.10	4.04	% 0.01
4	$4.425 \pm 0.1$	4.42	4.47	4.46	4.46	4.43	4.43	4.51	4.46	4.43	4.48	OK
5	$1.5 \times 45^\circ$	checked with bevel & Vernier & found OK										OK
6	$8.35 \pm 0.2$	8.23	8.24	8.16	8.25	8.30	8.27	8.27	8.34	8.22	8.29	OK
7	$6.80 \pm 0.1$	6.78	6.82	6.83	6.80	6.81	6.80	6.85	6.84	6.81	6.82	OK
8	$3.40 \pm 0.1$	the slot has shifted from centre unable to check										
9	$2.0 \pm 0.1$	2.05	2.09	2.09	2.06	2.04	2.04	2.09	2.06	2.02	2.09	OK
10	$1.0 \pm 0.1$	the slot has shifted from centre unable to check										
11	$4.00 \pm 0.2$	4.08	4.09	4.03	4.06	4.02	4.07	4.03	4.07	4.02	4.08	OK
12	$1.65 \pm 0.2$	1.69	1.69	1.56	1.45	1.49	1.49	1.46	1.47	1.55	1.51	OK
13	$0.12 \pm 0.1$	0.30	0.32	0.25	0.32	0.27	0.29	0.26	0.30	0.27	0.29	OK
14	$2.45 \pm 0.1$	2.78	2.76	2.70	2.73	2.79	2.68	2.59	2.72	2.68	2.66	% 0.14
15	$1.25 \pm 0.2$	1.19	1.13	1.20	1.19	1.20	1.20	1.24	1.19	1.12	1.16	OK
16	All corners R1.0 TYP	checked Visually R 1.0 All corners & found OK										OK
17	Punch Hole M4 X 0.7	checked with a TPG M4 X 0.7 (Go/NoGo: PNC 7585 / PPF 5687)										OK
18	minor $\phi$	3.35	3.37	3.35	3.35	3.36	3.36	3.39	3.36	3.36	3.37	OK
19	weld pip Angle $45^\circ$	checked with a bevel Protractor & found OK										OK
20												

CHECKED BY :- **Shubham**

APPROVED BY :-

PREVIOUS DATE :

PREVIOUS REPORT NO : **221559**

RECEIVED QTY

LOT 1 : **3842** nos.

LOT 2 : nos.

LOT 3 : nos.

LOT 4 : nos.

SIGN & Dt:-

**26-09-2025**

DATE:-

REMARK : 1) Due to extra force the shape has change.

2) observe marking line on slot surface & die marks

3) observe in some pc that slot has shifted from centre

4) Accepted as per previous Report after discussing with prashant sir