



# LAPORAN BAHAYA

Nama Pelapor/Reporter Name		INX Ref No. (INX Event No.)	
Bawo1			
Tanggal Date	5/11/25	Waktu Time	6:40
Dept. Penanggung Jawab/Responsible Dept.		Pengawas Area/Supervisor Area	
		Bawo1	

Lokasi Location	R1.120 Acc
Rincian Bahaya/Hazard details	

Cable yang menggantung  
terlalu rendah

## Tindakan Perbaikan Langsung/Immediate corrective actions

Gantung ke arah yang lebih  
tinggi saat dengan benang

## Tindakan Perbaikan yang disarankan/Suggested corrective actions



## LAPORAN BAHAYA

### Penilaian Risiko/*Risk Assessment*

(Diisi oleh pengawas/*Completed by Supervisor*)

Kemungkinan/ <i>Probability</i> :		Tingkat Risiko/ <i>Risk Rank</i> :	
Konsekuensi/ <i>Consequence</i> :			

### Tindakan perbaikan yang dilakukan/*Corrective Actions Suggested*

Area for corrective actions with horizontal dashed lines. A blue diagonal line is drawn across the section.

### Komentar/*Comments*

Area for comments with horizontal dashed lines. A blue diagonal line is drawn across the section.

Diselesaikan oleh/*Close out Report by*

Tanda Tangan Pengawas/ <i>Supervisor's Signature</i>		Tanggal/ <i>Date</i>	5/11/20
---	--	-------------------------	---------