



LAPORAN BAHAYA

Nama Pelapor/Reporter Name		INX Ref No. (INX Event No.)	
Ketut			
Tanggal Date	: 7.9.2025	Waktu Time	: 11.20
Dept. Penanggung Jawab/Responsible Dept.		Pengawas Area/Supervisor Area	
UG Mining		Hendri	
Lokasi Location	: RL120 M63		
Rincian Bahaya/Hazard details			
Rock bolt kedudukan clamp Pipa pemadam Menonjol			
Tindakan Perbaikan Langsung/Immediate corrective actions			
Melaporkan ke pengawas area.			
Tindakan Perbaikan yang disarankan/Suggested corrective actions			
Memasang safety line.			

**LAPORAN BAHAYA****Penilaian Risiko/Risk Assessment**

(Diisi oleh pengawas/Completed by Supervisor)

Kemungkinan/Probability :	E1	Tingkat Risiko/ Risk Rank :	R
Konsekuensi/Consequence :	E1		

Tindakan perbaikan yang dilakukan/Corrective Actions Suggested

Memasang safety line
supaya terlihat

Komentar/Comments

Sudah dilakukan

Diselesaikan oleh/Close out Report by

Tanda Tangan Pengawas/ Supervisor's Signature :	Handri S.	Tanggal/ Date :	08-09-25
--	-----------	--------------------	----------