



---

**Tab 72**  
**Fire Hall #18**

---



Corporation of the City of Kawartha Lakes:  
Sample Survey Table  
Fire Hall #18

Sample ID	Room Name/No. and Floor	Location of Sample	Type of Material	Location of Material	Condition of Material	Quantity of Material	Date	Fibrous Asbestos Content %			Comments, Notes, and/or Recommendations
								% Asbestos	Asbestos Type	Friable/Non-Friable	
AS613-1-09	Bay	east wall 1.5 m from floor 40 cm from south wall	Interior Trowelled Cement	throughout walls of bay and outside walls of washroom	good- some noted damaged areas	120 m <sup>2</sup>	18-Jun-09	<0.5			None
AS613-2-09		south east corner 1.5 m from floor at damage						<0.5			
AS613-3-09		west wall south side of west door at floor						<0.5			
AS613-4-09		east side of north doorway at floor						<0.5			
AS613-5-09		west wall at washroom doorway at floor						<0.5			
AS614-1-09	Bay	north of washroom door 15 cm from floor at hole	Drywall (Bay)	throughout ceiling and washroom of bay	good	135 m <sup>2</sup>	18-Jun-09	<0.5			None
AS614-2-09		bay ceiling above washroom door where wire penetrates ceiling						<0.5			
AS614-3-09		north east corner at ceiling where wire penetrates ceiling						<0.5			

Notes:

1. "NA" denotes not applicable.
2. "-" denotes not tested or information not required.




Corporation of the City of Kawartha Lakes  
Sample Survey Table  
Fire Hall #18

Sample ID	Room Name/No. and Floor	Location of Sample	Type of Material	Location of Material	Condition of Material	Quantity of Material	Date	Fibrous Asbestos Content %			Friable/Non-Friable	Comments, Notes, and/or Recommendations
								% Asbestos	Asbestos Type			
AS617-1-09	Exterior of the Bay	northeast corner of building at chest height						<0.5				
AS617-2-09		middle of east wall just north of south bay door near the ground						<0.5				
AS617-3-09		southeast corner of building on south wall near the ground	Exterior Trowelled Cement	outside walls of bay, now interior in connection to portable	good	120 m <sup>2</sup>	18-Jun-09	<0.5				None
AS617-4-09		middle of doorway into bay on south side						<0.5				
AS617-5-09		middle of doorway into bay on north side						<0.5				
AS618-1-09	Portable Main Area	north wall east side of windows						<0.5				
AS618-2-09		south wall behind light switch west of doorway into bay	Wall Paper (Portable)	throughout exterior walls	good	55 m <sup>2</sup>	18-Jun-09	<0.5				None
AS618-3-09		southwest corner of room south of doorway near the ceiling where damaged						<0.5				

Notes:

1. "NA" denotes not applicable.
2. "-" denotes not tested or information not required.



Corporation of the City of Kawartha Lakes  
Sample Survey Table  
Fire Hall #18

Sample ID	Room Name/No. and Floor	Location of Sample	Type of Material	Location of Material	Condition of Material	Quantity of Material	Date	Fibrous Asbestos Content %			Comments, Notes, and/or Recommendations
								% Asbestos	Asbestos Type	Friable/Non-Friable	
NA	Portable	sampling would have been destructive	Drywall Mud (portable)	ceiling screws	good	2 m <sup>2</sup>	18-Jun-09				could not locate mud other than the mud covering screws in the middle of the ceiling
NA	Bay	na	Cinderblock and Mortar	bay walls	good		18-Jun-09				

Notes:

1. "NA" denotes not applicable.
2. "-" denotes not tested or information not required.

All sample identification labels within photographs correspond with the sample numbers.



All sample identification labels within photographs correspond with the sample numbers.







All sample identification labels within photographs correspond with the sample numbers.

