

HITACHI SEMICONDUCTOR TECHNICAL UPDATE

Classification of Production	Development Environment			No	TN-EML-082A/E	
THEME	Information on a Malfunction and Version Update of the SH7750R E10A Emulator and the SH7751R E10A Emulator	Classification of Information	1. Spec change 2. Supplement of Documents 3. Limitation of Use	4. Change of Mask 5. Change of Production Line		
PRODUCT NAME	SH7750R SH7751R	Lot No. All lots	Reference Documents	None	Rev. —	Effective Date Permanent

A Timeout error occurred when a breakpoint has been set in the SH7750R E10A emulator and The SH7751R E10A emulator.

Type numbers of the target products:

SH7750R E10A emulator V1.00

Type number: HS7750RKCM01H
HS7750RKCI01H

SH7751R E10A emulator V1.00

Type number: HS7751RKCM01H
HS7751RKCI01H
HS7751RKCM02H
HS7751RKCI02H

[Malfunction]

When the EMODE bit in the CCR register is 1 and a breakpoint is used, a Timeout error will occur.

We will modify this malfunction and register the software on Hitachi's internet homepage.

If you need the updated version immediately, ask Hitachi's sales agent.

We will provide the file to be replaced in the floppy disk.

URL :

<http://www.hitachisemiconductor.com/sic/jsp/japan/eng/products/mpumcu/tool/download/e10a.html>