

HITACHI SEMICONDUCTOR TECHNICAL UPDATE

DATE	24th March, 1999	No.	TN-EML-040A/E
THEME	Malfunction of TELNET Connection in E8000 Emulator (HS8000EST02SR)		
CLASSIFICATION	<input checked="" type="checkbox"/> Spec. change <input type="checkbox"/> Limitation on Use <input type="checkbox"/> Supplement of Documents		
PRODUCT NAME	HS8000EST02SR (embedded in HS8000EST02H)	Lot No. etc.	V1.0
REFERENCE DOCUMENT	-	Effective Date	Permanent
		From	
<p>In the LAN interface of the E8000 emulator (HS8000EST02H), the TELNET may not be correctly connected in a part of workstations (HP9000-series HP-UX 10.20 and SPARC station Solaris 2.5).</p> <p>If the TELNET connection fails when the LAN interface of the E8000 emulator is used, contact Hitachi's sales department. We will improve the revision (V1.0A) of the E8000-monitor software.</p>			