

Authorized Field Change

AFC 06908

Date: August, 2006

Subject File: ENGINE

Subject: The Engine Dip Stick Tube Support Bracket and P-Clip must be Removed

Model: CF 500, CF 600

Start Date: 05/02/2006 End Date: 07/05/2006

DESCRIPTION

A small number of International® CF models were built with a frame mounted engine dip stick tube support.

SERVICE PROCEDURE

! WARNING – To avoid property damage, personal injury, or death, park the vehicle on a flat level surface, set the parking brake, turn the engine off, and chock the wheels.

1. Remove the engine dip stick tube frame mounted bracket and p-clip (Figure 1).



Figure 1 Remove Bracket and P-Clip Shown in Circle

Operation number must appear on all claims.

Table 1 Labor Information

Operation No.	Description	Time
A40-06908-1	Remove Dip Stick Bracket and P-Clip	0.5 Hr.

ADMINISTRATIVE PROCEDURE

Expense is to be charged to Warranty. Claims are to be submitted in the normal manner, making reference to Authorized Field Change Number G-06908.

It is important that the coding be completed properly to assist in processing the warranty claim. Complete instructions will be found in the Warranty Manual, Section 7-1. Special attention should be given to Items 39 through 44.

To assure this important improvement is made in a timely manner, all claims for G-06908 activity must be submitted by August 31, 2007 or within the normal warranty period for the vehicle, if after August 31, 2007.

GROUP	NOUN	C	WARR.	TP	PAD
GROUP Enter number G—	NOUN Leave blank	C (CAUSE) Enter either 1, 2, 3. (see below)	WARRANTY (Warranty Code) Enter 40.	TYPE PART Enter P for type part causing failure.	PAD Enter 100
		1. Inspected (No repair required).			
		2. Inspected and repaired.			
		3. Defective part from parts stock.			

Distribution: All except J-81

Reproduction: Not required.