



INTERNATIONAL TRUCK AND ENGINE CORPORATION
4201 WINFIELD ROAD, WARRENVILLE, IL 60555

TRUCK GROUP

RECALL REMINDER FOR SAFETY RECALL 02515

October 2004

Dear International Truck Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. International® has decided that a defect, which relates to motor vehicle safety, exists in the front and rear brakes on certain 9100i, 9200i, 9400i and 9900i models built from 7/22/02 through 8/16/02

The vehicle identified on the attached card fits this description. ***Our records show that you own this vehicle and were sent an initial Safety Recall Notification in December of 2002.*** Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Multiple bolts are used to hold the brake spiders or brake anchor plates tight to the axles. On the right side of these vehicles, the bolts and nuts were under-torqued at the assembly plant. The low torque may not provide the necessary clamp load on the fasteners to adequately secure the brake spider to the axle wheel end. This defect affects the right side of the vehicle only.

If the clamp load is not sufficient, the brake spider will move when the brakes are applied in either the forward or reverse direction. Such movement may cause individual brake components to fail or eventually fatigue the brake spider mounting bolts. If all the bolts fail due to fatigue, the result would be complete loss of braking at that wheel end. Reduced braking power could occur without warning and result in an extended stopping distance, which could result in loss of vehicle control, which in turn could cause a vehicular crash or accident, possibly resulting in property damage, personal injury or death.

In the event you no longer own the vehicle described on the card, please complete the card, fill in the new customer name and address if known, and return it to us. This information will allow us to update our records so that we can contact the current owner and you will not be contacted again regarding this recall.

Please contact your local International dealer to schedule an appointment and have the service procedure completed. Be prepared to read your vehicle identification number from your attached card when you call to schedule an appointment. The repair will be made without charge to you and may require approximately two (2) hours of repair time.

ALL VEHICLES IN THIS SAFETY RECALL MUST BE CORRECTED.

If the vehicle will not or cannot be corrected, please mark on the attached card the box which best describes why the vehicle will not be repaired, and return the postage-prepaid card to us.

We urge your prompt attention to the correction of this safety defect and apologize for any inconvenience this may cause you.

INTERNATIONAL TRUCK AND ENGINE CORPORATION

AUTHORIZATION FOR RECALL
SERVICE REMINDER

Model Name	Vehicle Identification Number (VIN)	TSR	Dealer Code	Campaign #



- Please check only one (1) of the following:
- 1 ☐ Vehicle inspected – no corrections necessary.
 - 2 ☐ Vehicle corrections completed.
 - 3 ☐ I do not own this vehicle any more.
(Please complete the NEW OWNER INFORMATION block)
 - 4 ☐ Service Not Desired. Reason: _____
 - 5 ☐ Vehicle Scrapped (junked). Will not return to public streets.
 - 6 ☐ Vehicle Stolen (whereabouts unknown).
 - 7 ☐ Vehicle exported from U.S. to another country.
(Please complete the NEW OWNER INFORMATION block)

New Owner Information

Name

Street

CityStateZip