

SERVICE MANUAL

SERVICE MANUAL SECTION

AUTOMATIC SLACK ADJUSTERS: ROCKWELL

Vendor: ROCKWELL, ArvinMeritor

Model: 2000

Model: 3000

Model: 4000

Model: 5000

Model: 8100

Model: 8200

Model: 8300

Model: 9100

Model: 9200

Model: 9300

Model: 9400

Model: 9600

Model: 9700

Model: 9800

S04006

10/26/2006

Table of Contents

DESCRIPTION..... 1

DESCRIPTION

For service procedures, go to the ArvinMeritor web site from the ISIS Suppliers listing.



WARNING – Brake Automatic Slack Adjusters (ASA's) should not need to be manually adjusted in service. ASA's should not routinely have to be adjusted to correct excessive pushrod stroke. Excessive stroke indicates that a problem exists with the foundation brake, ASA, brake actuator, other brake system components or their installation or adjustment.

In the event that a manual adjustment must be made (although this should not be a common practice), a service appointment and full foundation brake, ASA, and other brake system component inspection must be conducted as soon as possible to ensure the integrity of the overall brake system prior to returning the vehicle to service.

Failure to follow this Warning may result in property damage, personal injury or death.