



Photo 1 – Room 127



Photo 2 – Room 127

Sections of moisture damaged plaster ceilings were observed.



Photo 3 – Room 128
Sections of moisture damaged plaster ceilings were observed.



Photo 4 – Room 128
Sections of moisture damaged plaster ceilings were observed.



Photo 5 – Room 128 Closet
Water staining was observed on sections of the walls.



Photo 6 – Room 128 Storage Closet
An active leak was observed on the roof drain.



Photo 7 – Room 128
Moisture damaged plaster was observed around the skylights.



Photo 8 – Room 130
Sections of moisture damaged plaster ceilings were observed.



Photo 9 – Roof over Room 128



Photo 10 – Room 131

Sections of missing and moisture damaged plaster ceilings were observed.



Photo 11– Room 131

Sections of missing and moisture damaged plaster ceilings were observed.



Photo 12 – Cafeteria

Water damaged walls and stained ceiling tiles were observed.



Photo 13 –Cafeteria
Water damaged walls and stained ceiling tiles were observed



Photo 14 – Stairwell along Spruce Street
Water appeared to be seeping into the stairwell from the exterior sidewalk and steps.



Photo 15 – Stairwell along Spruce Street
Water appeared to be seeping into the stairwell from the exterior sidewalk and steps.



Photo 16 – Nurse's Exam Room A
Mold growth was observed on the bottom of the wooden sink cabinet.



Photo 17 – Nurse’s Exam Room A
Mold growth was observed on the bottom of the wooden sink cabinet.



Photo 18 – Nurse’s Exam Room A
Mold growth was observed on the bottom of the wooden sink cabinet.



Photo 19 – Hallway outside Room 334
Water stained ceiling tiles were observed.



Photo 20 – Room 321
Mold growth was observed on sections of the fiberglass pipe insulation.



Photo 21 – Room 321
Mold growth was observed on sections of the fiberglass pipe insulation.



Photo 22 – Room 321
Mold growth was observed on sections of the fiberglass pipe insulation.



Photo 23 – Room 322

A hole in the block wall was observed from repairs to the piping.



Photo 24 – Room 322

Mold growth was observed along the bottom of the gypsum wallboard.



Photo 25 – Room 322

Mold growth was observed along the bottom of the gypsum wallboard.



Photo 26 – Hallway outside Room 337
Water stained ceiling tiles were observed.



Photo 27 – Stairwell near Room 337
Sections of flaking paint and damaged concrete ceiling were observed.



Photo 28 – Stairwell near Room 337
Sections of flaking paint and damaged concrete ceiling were observed.



Photo 29 – Stairwell near Room 337
Sections of flaking paint and damaged concrete ceiling were observed.