



Photo 1 –Cafeteria



Photo 2 –Cafeteria
The humidity was elevated at 78%.




Photo 3 –Cafeteria
Mold growth was observed under the cafeteria tables.



Photo 4 – Cafeteria
Particulate accumulation on the return air grille and a moldy ceiling tile was observed.



Photo 5 – Cafeteria
Piano



Photo 6 – Cafeteria
Mold growth was observed in crevasses of the piano.



Photo 7 – Cafeteria
Mold growth was observed on the wooden doors and metal door frames.



Photo 8 – Cafeteria
Particulate accumulation was observed on the return air grilles.



Photo 9 – Stage
Suspect mold growth was observed on the flag.




Photo 10 – Cafeteria
Handicap Ramp



Photo 11– Cafeteria
Mold growth was observed on the handicap ramp.



Photo 12 – Cafeteria
Mold growth was observed on the portable steps in from of the stage.



Photo 13 – Cafeteria

Mold growth was observed on the cart and storage platforms under the stage.



Photo 14 – Cafeteria

Mold growth was observed on section of lower cinder block walls.



Photo 15 – Cafeteria

Mold was observed on sections of the lower cinder block walls.



Photo 16 – Cafeteria

A mold ceiling was observed by the 2nd grade exit door.



Photo 17 – Stage
Mold growth was observed on the electrical panel covers.



Photo 18 – Stage
Mold growth was observed on the podium.



Photo 19 – Stage
Mold growth was observed on the podium.



Photo 20 – Stage
Mold growth was observed on the piano seat.



Photo 21 – Stage
Mold growth was observed on the wooden door and metal door frame.



Photo 22 – Stage
Overhead Map



Photo 23 – Stage
Mold growth was observed on the overhead map housing and bottom of the map.



Photo 24 – Stage
Mold growth was observed on the fiberglass duct work.



Photo 25 – Small Staff Lunch Room




Photo 26 – Small Staff Lunch Room
Mold growth was observed on the fiberglass duct work.



Photo 27 – Small Teacher's Storage Room
Mold growth was observed on the metal storage cabinets, shelving and TV.



Photo 28 – Small Teacher's Storage Room
Mold growth was observed on the fiberglass duct insulation.



Photo 29 – Small Teacher's Storage Room
Mold growth was observed on the TV cabinet.



Photo 30 – Small Teacher's Storage Room
Mold growth was observed on the metal storage units.




Photo 31 –Operations Storage Room



Photo 32 –Operations Storage Room
Mold growth was observed on the fiberglass duct insulation.




Photo 33 – Kitchen Staff Area
Mold growth was observed on the coat rack.



Photo 34 – Kitchen Staff Area
Mold growth was observed on the coat rack.