



Photo 1 – Front of Building



Photo 2 – Front of Building



Photo 3 – Rear of Building




Photo 4 – Room 200



Photo 5 – Room 200  
Trash, debris, and mouse droppings were observed in the classroom sink.



Photo 6 – Room 200  
Mouse droppings were observed in the sink cabinet.





Photo 7 – Room 200  
Classroom unit ventilator



Photo 8 – Room 200  
A section of moisture damaged plaster was observed on the ceiling.



Photo 9 – Room 200  
Paint and plaster debris was observed on classroom materials.



Photo 10 – Room 200  
Paint and plaster debris was observed on classroom materials.



Photo 11– Room 200  
Paint and plaster debris was observed on the floor.



Photo 12 – Room 200




Photo 13 – Room 200  
The asthma first aid poster was posted in this room.




Photo 14 – Courtyard






Photo 15 –Courtyard  
Tree branches were growing close to the building and over the roof.



Photo 16 – Room 204  
Flaking paint and efflorescence were observed along the window wall.





Photo 17 – Room 204  
Mouse droppings were observed in the sink cabinet.



Photo 18 – Room 214



Photo 19 – Room 214

Trash and debris were observed on the floor around the pipe penetrations.



Photo 20 – Room 214

Air fresheners were observed in this room.




Photo 21 – Room 214  
A plug-in air freshener was observed in this room.



Photo 22 – Room 214  
Clutter was observed in the corner of the room.



Photo 23 – Room 214  
A flood occurred in this room impacting the area carpet.



Photo 24 – Room 214  
Mouse droppings and sunflower seeds were observed between the block wall and metal cabinet.





Photo 25 – Stairwell to School Yard  
Missing suspended ceiling tiles were noted.



Photo 26 – Stairwell to School Yard  
Missing suspended ceiling tiles were noted.



Photo 27 – School Yard Exit Doors




Photo 28 – Gymnasium Entry  
A missing ceiling tile was noted.



Photo 29 – Gymnasium



Photo 30 – Gymnasium

Dust accumulation was observed on the conduit and wall-mounted components.



Photo 31 – Gymnasium  
Heavy particulate loading was observed on the ventilation grilles.



Photo 32 – Gymnasium Office  
Mouse droppings were observed in the gym office.






Photo 33 – Gymnasium Office  
The return air filter and tray were not properly positioned.



Photo 34 – Gymnasium Office Restroom  
The floor drain was covered with duct tape to prevent odors.



Photo 35 – Cafetorium



Photo 36 – Cafetorium



Photo 37 – Cafetorium




Photo 38 – Stage



Photo 39 – Stage



Photo 40 – Stage





Photo 41 – Stage



Photo 42 – Stage



Photo 43 – IMC



Photo 44 – Room 104



Photo 45 – Room 104



Photo 46 – Room 104

A slow leak was observed on the classroom faucet.



Photo 47 – Room 104



Photo 48 – Room 104

Flaking paint was observed around the windows.





Photo 49 – Room 104  
Paint debris was observed on the window sill.



Photo 50 – Room 104  
Mold growth was observed on the pipe insulation.



Photo 51 – Room 104  
Mold growth was observed on the pipe insulation.



Photo 52 – Room 104




Photo 53 – Room 104  
The first aid asthma poster was noted in this room.



Photo 54 – IMC



Photo 55 – IMC  
Mouse droppings were observed under the cushions.



Photo 56 – IMC  
Mouse droppings were observed under the cushions.





Photo 57 – IMC

Water stained ceiling tiles were observed under the lower roof.



Photo 58 – Room 112

A significant amount of clutter was observed in this room.



Photo 59 – Room 112



Photo 60 – Room 112

A significant amount of clutter was observed in this room.



Photo 61 – Room 112  
This section of the radiator cover was not secured.




Photo 62 – Room 112



Photo 63 – Room 112  
Water staining and mold growth was observed on the pipe insulation.




Photo 64 – Room 112  
Classroom materials were blocking the unit ventilator.






Photo 65 – Room 112  
significant amount of clutter was observed in this room.



Photo 66 – Room 112  
significant amount of clutter was observed in this room.



Photo 67 – Room 112



Photo 68 – Room 112  
Mouse droppings were observed near the sink.



Photo 69 – Room 112  
Food waste was noted in the trash can.



Photo 70 – Room 112  
The first aid asthma poster was observed in this room.



Photo 71 – Main Entrance  
The door seals at this location were tight.



Photo 72 – Main Entrance





Photo 73 –Loading dock

A significant amount of trash accumulation was observed in and behind the dumpster.



Photo 74 – Loading dock

A significant amount of trash accumulation was observed in and behind the dumpster.