



Photo 1 – Gymnasium



Photo 2 – Gymnasium (northwest corner)



Photo 3 – Gymnasium (west)  
Water intrusion was reported from the main roof during heavy rainfall.




Photo 4 –Gymnasium (southwest)  
Water intrusion was reported form the southwest corner during heavy rainfall.



Photo 5 – Gymnasium (southwest)  
Buckets were placed in the closet to capture water.



Photo 6 – Gymnasium (northwest)  
Staining and suspect mold growth was observed on the top of the acoustical panel under the roof drain.



Photo 7 – Boy's Locker Room  
Missing suspended ceiling tiles were noted.



Photo 8 – Coach's Office  
Water stained ceiling tiles were observed.



Photo 9 – Coach's Office  
Water stained ceiling tiles and gypsum wall board was observed.



Photo 10 – Stage  
Water staining was observed on the wallboard located on the north and east wall.





Photo 11– Stage  
Minor cupping from water intrusion was observed on a section of the hardwood floor adjacent to the north wall.



Photo 12 – Gym Roof



Photo 13 – Gym Roof



Photo 14 – Gym Roof



Photo 15 – Stage Roof




Photo 16 – Stage Roof





Photo 17 – Stage Roof  
An open seam was observed on the flashing



Photo 18 –Cooling Tower Roof