



Photo 1 – Room 102

A freeze-up occurred on the classroom unit ventilator resulting in the loss of heat and water intrusion.



Photo 2 – Room 102

Delaminated sections of 9'x9' floor tile were observed from the water intrusion.



Photo 3 – Reading Intervention Room  
Water leaked through the ceiling resulting in delaminated 9"x9" floor tile.



Photo 4 – Reading Intervention Room  
Water stained ceiling tiles were observed.





Photo 5 – Reading Intervention Room



Photo 6 – Room 101

A freeze-up occurred on the classroom unit ventilator resulting in the loss of heat and water intrusion.



Photo 7 – Room 101

A freeze-up occurred on the classroom unit ventilator resulting in the loss of heat and water intrusion.



Photo 8 – Room 101

A freeze-up occurred on the classroom unit ventilator resulting in the loss of heat and water intrusion.





Photo 9 – Room 101  
Elevated moisture content was measured on the classroom bulletin board.



Photo 10 – Room 200  
A freeze-up occurred on the classroom unit ventilator resulting in the loss of heat and water intrusion.



Photo 11– Room 200  
Delaminated sections of 12”x12” floor tile were observed from the water intrusion.



Photo 12 – Room 205  
Delaminated sections of 12”x12” floor tile were observed from the water intrusion.