

SHROUD UPPER REINFORCEMENT REMOVAL [PANEL REPLACEMENT]

id098008927900

Symbol Mark

SYMBOL MARK	MEANING
●	SPOT WELDING


ac5wzb00000021

Removal Procedure

1. Drill the 4 locations shown in the figure.

Note

- When drilling the 4 locations shown in the figure, do not drill a hole all the way through or there could be a problem when installing the new part.



ac5wzb000000240

2. Remove the shroud upper reinforcement.