


## UPPER COWL SIDE REINFORCEMENT REMOVAL [PANEL REPLACEMENT]

id098008828500

### Symbol Mark

SYMBOL MARK	MEANING
	SPOT WELDING

ac5wzb00000029


### Removal Procedure

1. Drill the 13 locations indicated by (A) shown in the figure.
2. Drill the 8 locations indicated by (B) shown in the figure.

#### Note

- When a drill the 8 locations indicated by (B) shown in the figure, the through hole is not made in consideration of the workability at the installing.

3. Remove the upper cowl side reinforcement.



ac5wzb000000264