

SHROUD SIDE MEMBER INSTALLATION [PANEL REPLACEMENT]

id098008919100


Symbol Mark

SYMBOL MARK	MEANING
■	PLUG WELDING (ARC WELDING)

ac5wzb00000205

Installation Procedure

1. When installing new parts, measure and adjust the body as necessary to conform with standard dimensions.
2. Drill holes for the plug welding before installing the new parts.
3. After temporarily installing new parts, make sure the related parts fit properly.
4. Plug weld the 8 locations indicated by (A) and 2 locations indicated by (B) shown in the figure.



ac5wzb00000205

5. Plug weld the 3 locations indicated by (C) shown in the figure, then install the shroud side member.