

SIDE MEMBER REMOVAL [PANEL REPLACEMENT]

id098008928100

Symbol Mark

SYMBOL MARK	MEANING
●	SPOT WELDING


ac5wzb00000064

Removal Procedure

1. Drill the 45 locations shown in the figure.

Note

- When drilling, do not drill a hole all the way through or there could be a problem when installing the new part.



ac5uub00000054

2. Remove the side member.