


## DRIVE BELT INSPECTION [SKYACTIV-D 2.2]

id0110s5801500

### Note

- The drive belt deflection/tension inspection is not necessary with the adoption of the drive belt auto tensioner.

1. Verify that the indicator part of the engine side is within the normal range of the drive belt auto tensioner indicator mark.



ac5wzw00005256

- If it exceeds the limit, replace the drive belt. (See DRIVE BELT REMOVAL/INSTALLATION [SKYACTIV-D 2.2].)