

LOWER COWL SIDE REINFORCEMENT REMOVAL [PANEL REPLACEMENT]

id098008828700


Symbol Mark

SYMBOL MARK	MEANING
●	SPOT WELDING

ac5wzb00000033

Removal Procedure

1. Drill the 41 locations shown in the figure.



ac5wzb000000265

2. Remove the lower cowl side reinforcement.