


TORQUE BOX REMOVAL [PANEL REPLACEMENT]

id098008607100

Symbol Mark

SYMBOL MARK	MEANING
	SPOT WELDING


ac5wzb00000054

Removal Procedure

1. Drill the 19 locations indicated by (A) shown in the figure.


Note

- When drilling the 19 locations indicated by (A) shown in the figure, do not drill a hole all the way through or there could be a problem when installing the new part.



ac5wzb00000055

2. Drill the 8 locations indicated by (B) from the inside shown in the figure.



ac5wzb00000056

3. Remove the torque box.