



TAX INVOICE

GST Registration No.24-824-357

REPEAT PRINTOUT

Bill to: 9540

Gallagher Security M.E S.A.L
(Off Shore)
Abou Chakra Building
Same as RAK Ceramics Building
Second floor
PO Box 30053
Khaldeh - Lebanon 30053
Lebanon
Lebanon

Ship to: 9540

Gallagher Security M.E S.A.L
(Off Shore)
Abou Chakra Building
Khaldeh - Lebanon 30053
Lebanon
Lebanon

Ship Via:

FOB FOB - HAMILTON

Gross Weight:

0.3 KG

Invoice No./Date:

91422725 / 10-Feb-16

Order No./Date:

1042234 / 10-Feb-16

Purchase Order No.:

300164101

Delivery Note No.:

Name of Orderer:

Service Notification No:

300164101

Currency:

USD

Terms of payment:

Payment due 30th month, 2 mths after
Invoice date

Security Repair & Return

Item	Material	Description	Billed Quantity	Price	Amount
Repair Rep	Material	Material Description	Serial Number		
300164470	C300100	CONTROLLER 6000 STANDARD	1436401014		
010000	CDX_REPAIR_RETUR	Security Repair & Return	1.00 EA	0.01	0.01
010300	C300100	CONTROLLER 6000 STANDARD	1.00 EA	194.00	194.00
010500	CDX_REPAIR_RETUR	Security Repair & Return	1.00 EA	-0.01	-0.01
Total items					194.00
Freight					0.00
G.S.T.					0.00
Total Invoice					194.00

RGA 300164101 Ordered by Khodor

C300100 6000 Controller S/No: 1436401014

1 unit

*****REPAIR REPORT*****

Reported Fault: Not taking power

Fault Found:Shorted 12V input AND 12 volt output, R165 burnt on PCB

Corrective Action: Due to the amount of damage to this PCB it is

Send Wire Payment by MT100/MT103 Intermediary Bank: JP Morgan Chase Bank, New York SWIFT Address: CHASUS33 | Beneficiary Bank: ANZ Bank New Zealand Limited,
175, The Terrace, Wellington. SWIFT Address: ANZBNZ22 | Beneficiary Details: Gallagher Group Limited, 181 Kahikatea Drive, Hamilton 3206. Account Number: GALECT-USD00

Gallagher Group Ltd, 181 Kahikatea Drive, Hamilton 3206. Private Bag 3026,Hamilton 3240 New Zealand. Tel: 64 7 838 9800 Fax: 64 7 838 9801



Ship To: 9540
Gallagher Security M.E S.A.L
Abou Chakra Building

Document No./Date
91422725 / 10-Feb-16

Page 2

considered to be uneconomic to repair

Comments: has had external voltage applied.

Will send a serviced part at the fixed repair price.

*****REPAIR REPORT*****

