

1. On-Site Assessment: (Ref.: 14-29780)

- ▶ **Decision:** Accreditation has been reinstated for the affected scope.
- ▶ **Affected Scope:** Concrete methods C31 (Cylinders), C173, and C617 (7000 psi and below)
- ▶ **Reason:** The previous event was accidentally processed using report N-198 instead of N-298. The lab portal page has now been updated to reflect the lab's current accreditation.

2. On-Site Assessment: (Ref.: 14-29780)

- ▶ **Decision:** Accreditation has been granted for the affected scope.
- ▶ **Affected Scope:** Concrete method C192
- ▶ **Reason:** The previous event was accidentally processed using report N-198 instead of N-298. The lab portal page has now been updated to reflect the lab's current accreditation.

3. On-Site Assessment: (Ref.: 14-29780)

- ▶ **Decision:** Accreditation has been withdrawn for the affected scope.
- ▶ **Affected Scope:** Concrete method C31 and C78
- ▶ **Reason:** The previous event was accidentally processed using report N-198 instead of N-298. The lab portal page has now been updated to reflect the lab's current accreditation.