

we don't need R2 and R4 on the PCB, but a 3 pin header instead, for connecting the strain gauges

