

Morning meeting in the field

Department	Name	Content	Opinion
Production team	Mr Hoi	Change to new order of HK 2+2x0.32SHT 8 machines	
		BPW 1.92SHT-0.300UHT may be missing at the end of the month, so please try to handle it	
	Ms Dung		
	Mr Dat		
QC team	Mr Phuong	HK 2x0.30UHT pitch problems occurred too much during this time	Mr Hoi: Raw materials are problematic
		There are many welding machines in the TW department. If any constructions is missing, increase the number of welding machines for that constructions	Mr. Hoa rechecked this issue
	Mr Long		
Lab			
FD	Mr Hai		
	Mr Toan		
CP			
Mn	Tu	-New photo sensor has arrived from the maintenance department -While waiting for the wire clamp at the flange of the automatic TW machines, we need to attach the correct position of the flange according to the painted line on the machine.	-For machines that need to replace new sensors, the tool room will notify -Mr Hoi has already informed all employees about this issue
TW	Mr Sang	-Hankook 2x0.30UT wire break too many -Machine E-10 Reverser counter not correct	- BPW 1.92SHT problem now, Currently in the FD department there are also many broken wires -Mr Tu will be check this machine
	Mr Thuong	-Casumina 3x0.30HT(OC) adjust AH difficult -Machine G-6 often happen AH too hight -Spool affter painting not good	-Mr Hoa Checked the Casumina 3x0.30HT(OC) machines that have problems -Mr Hoi will have a meeting with the spool cleaning department to thoroughly grasp the issue of spool inspection
Tool	Mr Hoa		