



Technical Service Information


FORD CD4E

NO REVERSE & MOVES IN MANUAL LOW ONLY


COMPLAINT: After rebuild or solenoid body replacement, the vehicle exhibits a no reverse condition and moves forward in the manual low range only. If the wheels are off the ground, forward movement may be detected in other forward ranges as well.

CAUSE: The cause may be, the solenoid body filter gasket has been installed incorrectly.

CORRECTION: The solenoid body has two alignment dowel pins in opposite corners (See Figure 1). This allows the possibility of the solenoid filter gasket to be installed in two different positions. Figure 2 shows the **INCORRECT** positioning of the filter gasket. Figure 3 shows the **CORRECT** filter gasket position.




Copyright © 1998 ATSG



"INCORRECT" POSITIONING OF THE SOLENOID FILTER GASKET

Copyright © 1998 ATSG

Figure 2



"CORRECT" POSITIONING OF THE SOLENOID FILTER GASKET

Copyright © 1998 ATSG

Figure 3