



Technical Service Information


KM 175 HARSH UPSHIFTS (TPS)

COMPLAINT: Harsh upshift.

CAUSE: Broken or disconnected throttle position sensor wire or wires or faulty sensor or maladjusted.

CORRECTION: Ensure correct operation and adjustment of tps. Replace short harness with modified harness available from Mitsubishi

THROTTLE POSITION SENSOR (TPS)



Copyright © 2000 ATSG