



# Technical Service Information

## SUBARU 3 SPEED HARSH 1-2/3-2 SHUT

**COMPLAINT:** Harsh 1-2 and 3-2 shift.

**CAUSE:** Servo apply orifice missing.

**CORRECTION:** Install orifice in the apply servo tube on valve body end.




Figure 1

Copyright © 2000 ATSG