

TOYOTA A140 NO REVERSE AFTER OVERHAUL

COMPLAINT: No reverse all forward ranges good. (Overdrive planetary assembly changed during rebuild).

CAUSE: One cause may be a late planetary assembly installed in an early transaxle. The over-run clutches can no longer hold the planetary assembly as the hub for the clutches are in different location.

CORRECTION: Install the correct planetary assembly.




Figure 1