



Technical Service Information

THM 4L80-E/4L80-EHD SPEED SENSOR HARNESS REPAIR KIT

There is now available from General Motors, a new Speed Sensor Harness Repair Kit, available under OEM part number 12101899, to fit all THM 4L80-E/4L80-EHD transmissions (See Figure 1).




Figure 1