

NISSAN E/L4N71B SHIFTS TO O.D. REGARDLESS OF CANCEL SWITCH

COMPLAINT: Transmission shifts into O.D. regardless of O.D. control switch position.

CAUSE: The cause may be the small "O" ring missing, or mis-installed in the groove of the O.D. cancel solenoid. The small "O" ring goes BEHIND the O.D. cancel solenoid, as shown in Figure 1, and seals against the bottom of the case bore (See Figure 1).

CORRECTION: Install "O" ring in proper location as shown in Figure 1.




Figure 1