



Technical Service Information


TOYOTA A-40 SERIES

HARSH 1-2 SHIFT

COMPLAINT: HARSH 1-2 SHIFT

CAUSE: MISSING VITON CHECK BALL

CORRECTION: INSTALL CHECK BALL IN CORRECT LOCATION



Copyright © 2000 ATSG

Figure1

AUTOMATIC TRANSMISSION SERVICE GROUP

88-67
Page 1 of 1